


 Search ...

PRODUCTS | APPLICATIONS | DESIGN SUPPORT | TRAINING | SAMPLE AND BUY | ABOUT
US | CONTACT US | myMicrochip Login

Product Change Notification - JAON-02ILOD785

Date: 07 Jun 2016
Product Category: Micrel
Notification subject: End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.
Notification text: **PCN Status:**
End of Life (EOL) notification

Microchip Part Numbers Affected:

Please open the attachments found in the attachments field below labeled as PCN_#_Affected_CPN.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

Description of EOL:

Various Micrel catalog part numbers (CPN) will be moving to End of Life (EOL) effective today. These catalog part numbers are no longer offered after January 31, 2017. Replacement parts, if available, are listed in the affected part numbers attachments. Please observe the notes, in the attachment, regarding the replacement parts to identify differences between the EOL CPN and the replacements.

Reason for EOL:

The devices listed in the attachment will not be transferred at Microchip Fabrication sites using 8 inch wafers therefore Microchip will no longer have manufacturing support.

Estimated Effective Dates:

Customers affected by this EOL notice are advised to place last time buy orders (LTB) as follows:
 Last date for bookings (LTB): July 30, 2016
 Last date for shipments (LTS): January 31, 2017

Revision History:

June 7, 2016: Initial release of notification.

Attachment(s): [PCN_JAON-02ILOD785_Affected_CPN.pdf](#)
[PCN_JAON-02ILOD785_Affected_CPN.xls](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."



Products | Applications | Design Support | Training | Sample and Buy | About Us |
Contact Us | Legal | Investors | Careers | Support



©Copyright 1998-2016 Microchip Technology Inc. All rights reserved. Shanghai ICP
Recordal No.09049794

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|---|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY100E016JY | Contact Your Local Sales Office | NA |
| SY100E101JY | Contact Your Local Sales Office | NA |
| SY100E104JY | Contact Your Local Sales Office | NA |
| SY100E107JZ | Contact Your Local Sales Office | NA |
| SY100E111AEJY | Contact Your Local Sales Office | NA |
| SY100E111AEJY-TR | Contact Your Local Sales Office | NA |
| SY100E111AJY | Contact Your Local Sales Office | NA |
| SY100E111AJY-TR | Contact Your Local Sales Office | NA |
| SY100E111JY | Contact Your Local Sales Office | NA |
| SY100E111LEJY | Contact Your Local Sales Office | NA |
| SY100E111LEJY-TR | Contact Your Local Sales Office | NA |
| SY100E111LJY | Contact Your Local Sales Office | NA |
| SY100E111LJY-TR | Contact Your Local Sales Office | NA |
| SY100E112JY | Contact Your Local Sales Office | NA |
| SY100E116JY | Contact Your Local Sales Office | NA |
| SY100E116JY-TR | Contact Your Local Sales Office | NA |
| SY100E122JY | Contact Your Local Sales Office | NA |
| SY100E131JY | Contact Your Local Sales Office | NA |
| SY100E131JY-TR | Contact Your Local Sales Office | NA |
| SY100E136JZ | Contact Your Local Sales Office | NA |
| SY100E137JZ | Contact Your Local Sales Office | NA |
| SY100E141JY | Contact Your Local Sales Office | NA |
| SY100E141JY-TR | Contact Your Local Sales Office | NA |
| SY100E142JZ | Contact Your Local Sales Office | NA |
| SY100E143JZ | Contact Your Local Sales Office | NA |
| SY100E151JZ | Contact Your Local Sales Office | NA |
| SY100E155JZ | Contact Your Local Sales Office | NA |
| SY100E157JY | Contact Your Local Sales Office | NA |
| SY100E158JZ | Contact Your Local Sales Office | NA |
| SY100E163JZ | Contact Your Local Sales Office | NA |
| SY100E164JZ | Contact Your Local Sales Office | NA |
| SY100E166JZ | Contact Your Local Sales Office | NA |
| SY100E171JZ | Contact Your Local Sales Office | NA |
| SY100E196JY | Contact Your Local Sales Office | NA |

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|---|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY100E404JZ | Contact Your Local Sales Office | NA |
| SY100E417JY | Contact Your Local Sales Office | NA |
| SY100E417JY-TR | Contact Your Local Sales Office | NA |
| SY100E445JZ | Contact Your Local Sales Office | NA |
| SY100E446JZ | Contact Your Local Sales Office | NA |
| SY100E452JY | Contact Your Local Sales Office | NA |
| SY100E452JY-TR | Contact Your Local Sales Office | NA |
| SY100E457JZ | Contact Your Local Sales Office | NA |
| SY100EL01ZG | Contact Your Local Sales Office | NA |
| SY100EL01ZG-TR | Contact Your Local Sales Office | NA |
| SY100EL04ZG | Contact Your Local Sales Office | NA |
| SY100EL04ZG-TR | Contact Your Local Sales Office | NA |
| SY100EL05ZG | Contact Your Local Sales Office | NA |
| SY100EL07ZG | Contact Your Local Sales Office | NA |
| SY100EL07ZG-TR | Contact Your Local Sales Office | NA |
| SY100EL1003ZG | Contact Your Local Sales Office | NA |
| SY100EL12ZG | Contact Your Local Sales Office | NA |
| SY100EL15ZG | Contact Your Local Sales Office | NA |
| SY100EL15ZG-TR | Contact Your Local Sales Office | NA |
| SY100EL16VAZG | Contact Your Local Sales Office | NA |
| SY100EL16VAZG-TR | Contact Your Local Sales Office | NA |
| SY100EL16VBKG | Contact Your Local Sales Office | NA |
| SY100EL16VBKG-TR | Contact Your Local Sales Office | NA |
| SY100EL16VOKG | Contact Your Local Sales Office | NA |
| SY100EL16VSKG | Contact Your Local Sales Office | NA |
| SY100EL16VSKG-TR | Contact Your Local Sales Office | NA |
| SY100EL31ZG | Contact Your Local Sales Office | NA |
| SY100EL33ZG | Contact Your Local Sales Office | NA |
| SY100EL34ZG | Contact Your Local Sales Office | NA |
| SY100EL34ZG-TR | Contact Your Local Sales Office | NA |
| SY100EL35ZG | Contact Your Local Sales Office | NA |
| SY100EL38LZG | Contact Your Local Sales Office | NA |
| SY100EL38LZG-TR | Contact Your Local Sales Office | NA |
| SY100EL38ZG | Contact Your Local Sales Office | NA |

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|---|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY100EL51ZG | Contact Your Local Sales Office | NA |
| SY100EL51ZG-TR | Contact Your Local Sales Office | NA |
| SY100EL52ZG | Contact Your Local Sales Office | NA |
| SY100EL52ZG-TR | Contact Your Local Sales Office | NA |
| SY100EL57LZG | Contact Your Local Sales Office | NA |
| SY100EL57LZG-TR | Contact Your Local Sales Office | NA |
| SY100EL57ZG | Contact Your Local Sales Office | NA |
| SY100EL57ZG-TR | Contact Your Local Sales Office | NA |
| SY100EL58ZG | Contact Your Local Sales Office | NA |
| SY100EL58ZG-TR | Contact Your Local Sales Office | NA |
| SY100EL90VZG | Contact Your Local Sales Office | NA |
| SY100EL90VZG-TR | Contact Your Local Sales Office | NA |
| SY100EL91LZG | Contact Your Local Sales Office | NA |
| SY100EL91LZG-TR | Contact Your Local Sales Office | NA |
| SY100EL91ZG | Contact Your Local Sales Office | NA |
| SY100EL92ZG | Contact Your Local Sales Office | NA |
| SY100EL92ZG-TR | Contact Your Local Sales Office | NA |
| SY100ELT20VZG | Contact Your Local Sales Office | NA |
| SY100ELT20VZG-TR | Contact Your Local Sales Office | NA |
| SY100ELT21ZG | Contact Your Local Sales Office | NA |
| SY100ELT21ZG-TR | Contact Your Local Sales Office | NA |
| SY100ELT24ZG | Contact Your Local Sales Office | NA |
| SY100ELT24ZG-TR | Contact Your Local Sales Office | NA |
| SY100ELT25ZG | Contact Your Local Sales Office | NA |
| SY100ELT25ZG-TR | Contact Your Local Sales Office | NA |
| SY100ELT28ZG | Contact Your Local Sales Office | NA |
| SY100ELT982KG | Contact Your Local Sales Office | NA |
| SY100EP140LZG | Contact Your Local Sales Office | NA |
| SY100EP140LZG-TR | Contact Your Local Sales Office | NA |
| SY100EP14AUKG | Contact Your Local Sales Office | NA |
| SY100EP16UKG | Contact Your Local Sales Office | NA |
| SY100EP16UMG-TR | Contact Your Local Sales Office | NA |
| SY100EP16UZG | Contact Your Local Sales Office | NA |
| SY100EP16VKG | Contact Your Local Sales Office | NA |

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|---|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY100EP16VMG-TR | Contact Your Local Sales Office | NA |
| SY100EP16VSKY | Contact Your Local Sales Office | NA |
| SY100EP16VSKY-TR | Contact Your Local Sales Office | NA |
| SY100EP16VZG | Contact Your Local Sales Office | NA |
| SY100EP16VZG-TR | Contact Your Local Sales Office | NA |
| SY100EP196VTG | Contact Your Local Sales Office | NA |
| SY100EP196VTG-TR | Contact Your Local Sales Office | NA |
| SY100EP210UTG | Contact Your Local Sales Office | NA |
| SY100EP32VZG | Contact Your Local Sales Office | NA |
| SY100EP32VZG-TR | Contact Your Local Sales Office | NA |
| SY100EP33VZG | Contact Your Local Sales Office | NA |
| SY100EP33VZG-TR | Contact Your Local Sales Office | NA |
| SY100EP451LTG | Contact Your Local Sales Office | NA |
| SY100EP58VKG | Contact Your Local Sales Office | NA |
| SY100EP58VKG-TR | Contact Your Local Sales Office | NA |
| SY100EP58VZG | Contact Your Local Sales Office | NA |
| SY100EPT20VKG | Contact Your Local Sales Office | NA |
| SY100EPT20VKG-TR | Contact Your Local Sales Office | NA |
| SY100EPT28LZG | Contact Your Local Sales Office | NA |
| SY100EPT28LZG-TR | Contact Your Local Sales Office | NA |
| SY100H600JZ | Contact Your Local Sales Office | NA |
| SY100H601JZ | Contact Your Local Sales Office | NA |
| SY100H602JZ | Contact Your Local Sales Office | NA |
| SY100H641JZ | Contact Your Local Sales Office | NA |
| SY100H641LJZ | Contact Your Local Sales Office | NA |
| SY100H641LJZ-TR | Contact Your Local Sales Office | NA |
| SY100H646LJZ | Contact Your Local Sales Office | NA |
| SY100H841LZH | Contact Your Local Sales Office | NA |
| SY100H841ZH | Contact Your Local Sales Office | NA |
| SY100H842LZG | Contact Your Local Sales Office | NA |
| SY100H842ZH | Contact Your Local Sales Office | NA |
| SY100HA643JY | Contact Your Local Sales Office | NA |
| SY100S304JZ | Contact Your Local Sales Office | NA |
| SY100S307JY | Contact Your Local Sales Office | NA |

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|---|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY100S307JZ | Contact Your Local Sales Office | NA |
| SY100S314JY | Contact Your Local Sales Office | NA |
| SY100S314JZ | Contact Your Local Sales Office | NA |
| SY100S322JZ | Contact Your Local Sales Office | NA |
| SY100S324JY | Contact Your Local Sales Office | NA |
| SY100S324JY-TR | Contact Your Local Sales Office | NA |
| SY100S325JY | Contact Your Local Sales Office | NA |
| SY100S325JY-TR | Contact Your Local Sales Office | NA |
| SY100S331JY | Contact Your Local Sales Office | NA |
| SY100S331JZ | Contact Your Local Sales Office | NA |
| SY100S351JY | Contact Your Local Sales Office | NA |
| SY100S351JZ | Contact Your Local Sales Office | NA |
| SY100S363JZ | Contact Your Local Sales Office | NA |
| SY100S366JZ | Contact Your Local Sales Office | NA |
| SY100S370JZ | Contact Your Local Sales Office | NA |
| SY100S391JZ | Contact Your Local Sales Office | NA |
| SY100S391JZ-TR | Contact Your Local Sales Office | NA |
| SY100S811JZ | Contact Your Local Sales Office | NA |
| SY100S811ZH | Contact Your Local Sales Office | NA |
| SY100S811ZH-TR | Contact Your Local Sales Office | NA |
| SY100S815ZH | Contact Your Local Sales Office | NA |
| SY100S815ZH-TR | Contact Your Local Sales Office | NA |
| SY100S834ZG | Contact Your Local Sales Office | NA |
| SY100S838LZG | Contact Your Local Sales Office | NA |
| SY100S838LZG-TR | Contact Your Local Sales Office | NA |
| SY100S838ZG | Contact Your Local Sales Office | NA |
| SY100S838ZG-TR | Contact Your Local Sales Office | NA |
| SY100S839VZG | Contact Your Local Sales Office | NA |
| SY100S839VZG-TR | Contact Your Local Sales Office | NA |
| SY100S863JZ | Contact Your Local Sales Office | NA |
| SY10E016JY | Contact Your Local Sales Office | NA |
| SY10E016JY-TR | Contact Your Local Sales Office | NA |
| SY10E101JY | Contact Your Local Sales Office | NA |
| SY10E104JY | Contact Your Local Sales Office | NA |

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|---|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY10E104JY-TR | Contact Your Local Sales Office | NA |
| SY10E107JZ | Contact Your Local Sales Office | NA |
| SY10E107JZ-TR | Contact Your Local Sales Office | NA |
| SY10E111AEJY | Contact Your Local Sales Office | NA |
| SY10E111AJY | Contact Your Local Sales Office | NA |
| SY10E111JY | Contact Your Local Sales Office | NA |
| SY10E111JY-TR | Contact Your Local Sales Office | NA |
| SY10E111LEJY | Contact Your Local Sales Office | NA |
| SY10E111LEJY-TR | Contact Your Local Sales Office | NA |
| SY10E111LEJZ | Contact Your Local Sales Office | NA |
| SY10E111LEJZ-TR | Contact Your Local Sales Office | NA |
| SY10E111LJZ | Contact Your Local Sales Office | NA |
| SY10E112JY | Contact Your Local Sales Office | NA |
| SY10E116JY | Contact Your Local Sales Office | NA |
| SY10E116JY-TR | Contact Your Local Sales Office | NA |
| SY10E122JY | Contact Your Local Sales Office | NA |
| SY10E131JY | Contact Your Local Sales Office | NA |
| SY10E131JY-TR | Contact Your Local Sales Office | NA |
| SY10E137JZ | Contact Your Local Sales Office | NA |
| SY10E141JY | Contact Your Local Sales Office | NA |
| SY10E141JZ | Contact Your Local Sales Office | NA |
| SY10E142JY | Contact Your Local Sales Office | NA |
| SY10E143JZ | Contact Your Local Sales Office | NA |
| SY10E143JZ-TR | Contact Your Local Sales Office | NA |
| SY10E151JY | Contact Your Local Sales Office | NA |
| SY10E157JY | Contact Your Local Sales Office | NA |
| SY10E163JZ | Contact Your Local Sales Office | NA |
| SY10E164JZ | Contact Your Local Sales Office | NA |
| SY10E195JZ | Contact Your Local Sales Office | NA |
| SY10E195JZ-TR | Contact Your Local Sales Office | NA |
| SY10E446JZ | Contact Your Local Sales Office | NA |
| SY10E451JY | Contact Your Local Sales Office | NA |
| SY10E457JZ | Contact Your Local Sales Office | NA |
| SY10EL01ZG | Contact Your Local Sales Office | NA |

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|---|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY10EL01ZG-TR | Contact Your Local Sales Office | NA |
| SY10EL04ZG | Contact Your Local Sales Office | NA |
| SY10EL07ZG | Contact Your Local Sales Office | NA |
| SY10EL1189ZG | Contact Your Local Sales Office | NA |
| SY10EL11VZG | Contact Your Local Sales Office | NA |
| SY10EL11VZG-TR | Contact Your Local Sales Office | NA |
| SY10EL15ZG | Contact Your Local Sales Office | NA |
| SY10EL16VAZG | Contact Your Local Sales Office | NA |
| SY10EL16VBZG | Contact Your Local Sales Office | NA |
| SY10EL16VCKG | Contact Your Local Sales Office | NA |
| SY10EL16VCKG-TR | Contact Your Local Sales Office | NA |
| SY10EL16VCZG | Contact Your Local Sales Office | NA |
| SY10EL16VKG | Contact Your Local Sales Office | NA |
| SY10EL16VZG | Contact Your Local Sales Office | NA |
| SY10EL16VZG-TR | Contact Your Local Sales Office | NA |
| SY10EL31ZG | Contact Your Local Sales Office | NA |
| SY10EL31ZG-TR | Contact Your Local Sales Office | NA |
| SY10EL32VZG | Contact Your Local Sales Office | NA |
| SY10EL33LZG | Contact Your Local Sales Office | NA |
| SY10EL33ZG | Contact Your Local Sales Office | NA |
| SY10EL34LZG | Contact Your Local Sales Office | NA |
| SY10EL34LZG-TR | Contact Your Local Sales Office | NA |
| SY10EL34ZG | Contact Your Local Sales Office | NA |
| SY10EL34ZG-TR | Contact Your Local Sales Office | NA |
| SY10EL35ZG | Contact Your Local Sales Office | NA |
| SY10EL57ZG | Contact Your Local Sales Office | NA |
| SY10EL57ZG-TR | Contact Your Local Sales Office | NA |
| SY10EL58ZG | Contact Your Local Sales Office | NA |
| SY10EL58ZG-TR | Contact Your Local Sales Office | NA |
| SY10EL89ZG | Contact Your Local Sales Office | NA |
| SY10EL89ZG-TR | Contact Your Local Sales Office | NA |
| SY10ELT20VZG | Contact Your Local Sales Office | NA |
| SY10ELT21LZG | Contact Your Local Sales Office | NA |
| SY10ELT21ZG | Contact Your Local Sales Office | NA |

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|---|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY10ELT22LZG | Contact Your Local Sales Office | NA |
| SY10ELT22ZG | Contact Your Local Sales Office | NA |
| SY10ELT22ZG-TR | Contact Your Local Sales Office | NA |
| SY10ELT23LZG | Contact Your Local Sales Office | NA |
| SY10ELT23LZG-TR | Contact Your Local Sales Office | NA |
| SY10ELT23ZG | Contact Your Local Sales Office | NA |
| SY10ELT23ZG-TR | Contact Your Local Sales Office | NA |
| SY10EP01VKG | Contact Your Local Sales Office | NA |
| SY10EP01VZG | Contact Your Local Sales Office | NA |
| SY10EP01VZG-TR | Contact Your Local Sales Office | NA |
| SY10EP05VKG | Contact Your Local Sales Office | NA |
| SY10EP05VKG-TR | Contact Your Local Sales Office | NA |
| SY10EP08VKG | Contact Your Local Sales Office | NA |
| SY10EP08VKG-TR | Contact Your Local Sales Office | NA |
| SY10EP08VZG | Contact Your Local Sales Office | NA |
| SY10EP08VZG-TR | Contact Your Local Sales Office | NA |
| SY10EP16UKG | Contact Your Local Sales Office | NA |
| SY10EP16UMG-TR | Contact Your Local Sales Office | NA |
| SY10EP16UZG | Contact Your Local Sales Office | NA |
| SY10EP16VKG | Contact Your Local Sales Office | NA |
| SY10EP16VKG-TR | Contact Your Local Sales Office | NA |
| SY10EP16VZG | Contact Your Local Sales Office | NA |
| SY10EP16VZG-TR | Contact Your Local Sales Office | NA |
| SY10EP31VKG | Contact Your Local Sales Office | NA |
| SY10EP31VKG-TR | Contact Your Local Sales Office | NA |
| SY10EP32VKG | Contact Your Local Sales Office | NA |
| SY10EP32VKG-TR | Contact Your Local Sales Office | NA |
| SY10EP32VZG | Contact Your Local Sales Office | NA |
| SY10EP32VZG-TR | Contact Your Local Sales Office | NA |
| SY10EP33VKG-TR | Contact Your Local Sales Office | NA |
| SY10EP33VZG | Contact Your Local Sales Office | NA |
| SY10EP33VZG-TR | Contact Your Local Sales Office | NA |
| SY10EP52VKG | Contact Your Local Sales Office | NA |
| SY10EP52VKG-TR | Contact Your Local Sales Office | NA |

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|---|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY10EP52VZG | Contact Your Local Sales Office | NA |
| SY10EP52VZG-TR | Contact Your Local Sales Office | NA |
| SY10EP53VKG | Contact Your Local Sales Office | NA |
| SY10EP53VKG-TR | Contact Your Local Sales Office | NA |
| SY10EPT20VKG | Contact Your Local Sales Office | NA |
| SY10EPT20VZG | Contact Your Local Sales Office | NA |
| SY10EPT20VZG-TR | Contact Your Local Sales Office | NA |
| SY10EPT23LKG | Contact Your Local Sales Office | NA |
| SY10EPT28LKG | Contact Your Local Sales Office | NA |
| SY10EPT28LZG | Contact Your Local Sales Office | NA |
| SY10EPT28LZG-TR | Contact Your Local Sales Office | NA |
| SY10H350JZ | Contact Your Local Sales Office | NA |
| SY10H350JZ-TR | Contact Your Local Sales Office | NA |
| SY10H601JZ | Contact Your Local Sales Office | NA |
| SY10H606JZ | Contact Your Local Sales Office | NA |
| SY10H607JZ | Contact Your Local Sales Office | NA |
| SY10H641JZ | Contact Your Local Sales Office | NA |
| SY10H841ZH | Contact Your Local Sales Office | NA |
| SY10H842LZH | Contact Your Local Sales Office | NA |
| SY10H842ZH | Contact Your Local Sales Office | NA |
| SY54016ARMG-TR | Contact Your Local Sales Office | NA |
| SY54016RMG-TR | Contact Your Local Sales Office | NA |
| SY54017RMG | Contact Your Local Sales Office | NA |
| SY54017RMG-TR | Contact Your Local Sales Office | NA |
| SY54023ARMG | Contact Your Local Sales Office | NA |
| SY54023ARMG-TR | Contact Your Local Sales Office | NA |
| SY54023RMG | Contact Your Local Sales Office | NA |
| SY54023RMG-TR | Contact Your Local Sales Office | NA |
| SY55851AUKG | Contact Your Local Sales Office | NA |
| SY55851AUKG-TR | Contact Your Local Sales Office | NA |
| SY55854UYY | Contact Your Local Sales Office | NA |
| SY55854UYY-TR | Contact Your Local Sales Office | NA |
| SY55856UHG | Contact Your Local Sales Office | NA |
| SY56016RMG-TR | Contact Your Local Sales Office | NA |

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|---|--|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY56020XRMG | Contact Your Local Sales Office | NA |
| SY56023RMG | Contact Your Local Sales Office | NA |
| SY56028XRMG | Contact Your Local Sales Office | NA |
| SY56028XRMG-TR | Contact Your Local Sales Office | NA |
| SY56040ARMY | Contact Your Local Sales Office | NA |
| SY56040ARMY-TR | Contact Your Local Sales Office | NA |
| SY56216RMG | Contact Your Local Sales Office | NA |
| SY56216RMG-TR | Contact Your Local Sales Office | NA |
| SY58025UMG | Contact Your Local Sales Office | NA |
| SY58025UMG-TR | Contact Your Local Sales Office | NA |
| SY58027UMG | Contact Your Local Sales Office | NA |
| SY58027UMG-TR | Contact Your Local Sales Office | NA |
| SY58030UMG | Contact Your Local Sales Office | NA |
| SY58030UMG-TR | Contact Your Local Sales Office | NA |
| SY58037UMY | Contact Your Local Sales Office | NA |
| SY58037UMY-TR | Contact Your Local Sales Office | NA |
| SY58039UMY | Contact Your Local Sales Office | NA |
| SY58602UMG-TR | Contact Your Local Sales Office | NA |
| SY58620LMG | Contact Your Local Sales Office | NA |
| SY58620LMG-TR | Contact Your Local Sales Office | NA |
| SY58621LMG | Contact Your Local Sales Office | NA |
| SY58621LMG-TR | Contact Your Local Sales Office | NA |
| SY58626LMH | Contact Your Local Sales Office | NA |
| SY58626LMH-TR | Contact Your Local Sales Office | NA |
| SY58627LMG | Contact Your Local Sales Office | NA |
| SY604JZ | Contact Your Local Sales Office | NA |
| SY68730ZZ | Contact Your Local Sales Office | NA |
| SY68730ZZ-TR | Contact Your Local Sales Office | NA |
| SY69753LHG | SY69753ALHG | Drop-in Replacement Contact Your Local Sales Office |
| SY69753LHG-TR | SY69753ALHG | Drop-in Replacement Contact Your Local Sales Office |
| SY69952ZH | Contact Your Local Sales Office | NA |
| SY733021UZG | Contact Your Local Sales Office | NA |

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|---|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY733021UZG-TR | Contact Your Local Sales Office | NA |
| SY733940UTZ | Contact Your Local Sales Office | NA |
| SY733940UTZ-TR | Contact Your Local Sales Office | NA |
| SY73551LZG | Contact Your Local Sales Office | NA |
| SY73551LZG-TR | Contact Your Local Sales Office | NA |
| SY84402LMG-TR | Contact Your Local Sales Office | NA |
| SY84403BLMG-TR | Contact Your Local Sales Office | NA |
| SY87700LHG | SY87700ALHG, SY87700ALZG | Drop-in Replacement |
| | | Contact Your Local Sales Office |
| SY87700LHG-TR | SY87700ALHG, SY87700ALZG | Drop-in Replacement |
| | | Contact Your Local Sales Office |
| SY87700LZG | SY87700ALHG, SY87700ALZG | Drop-in Replacement |
| | | Contact Your Local Sales Office |
| SY87700VHH | SY87701ALZG , SY87700ALHG | Drop-in Replacement |
| | | Contact Your Local Sales Office |
| SY87700VZH | SY87701ALZG , SY87700ALHG | Drop-in Replacement |
| | | Contact Your Local Sales Office |
| SY87700VZH-TR | SY87701ALZG , SY87700ALHG | Drop-in Replacement |
| | | Contact Your Local Sales Office |
| SY87701LHG | Contact Your Local Sales Office | NA |
| SY87701VHH | SY87701ALHG, SY87701ALZG | Drop-in Replacement |
| | | Contact Your Local Sales Office |
| SY87701VZH | SY87701ALHG, SY87701ALZG | Drop-in Replacement |
| | | Contact Your Local Sales Office |
| SY87701VZH-TR | SY87701ALHG, SY87701ALZG | Drop-in Replacement |
| | | Contact Your Local Sales Office |
| SY87721LHY | Contact Your Local Sales Office | NA |
| SY87725LHY | Contact Your Local Sales Office | NA |
| SY88232LMG | Contact Your Local Sales Office | NA |
| SY88307BLEY | Contact Your Local Sales Office | NA |
| SY88307BLMG | Contact Your Local Sales Office | NA |
| SY88309BLEY | Contact Your Local Sales Office | NA |
| SY88343HLMG | Contact Your Local Sales Office | NA |
| SY88347DLEY | Contact Your Local Sales Office | NA |

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|---|--|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY88347DLEY-TR | Contact Your Local Sales Office | NA |
| SY88722VKG | SY88922VKG | Drop-in Replacement Contact Your Local Sales Office |
| SY88722VKG-TR | SY88922VKG | Drop-in Replacement Contact Your Local Sales Office |
| SY88782LMG | SY88982LMG | Drop-in Replacement Contact Your Local Sales Office |
| SY88782LMG-TR | SY88982LMG-TR | Drop-in Replacement Contact Your Local Sales Office |
| SY88808LMH | Contact Your Local Sales Office | NA |
| SY88843VEY | Contact Your Local Sales Office | NA |
| SY88843VEY-TR | Contact Your Local Sales Office | NA |
| SY88843VMG | Contact Your Local Sales Office | NA |
| SY88843VMG-TR | Contact Your Local Sales Office | NA |
| SY88893VKG | Contact Your Local Sales Office | NA |
| SY88923VKG | Contact Your Local Sales Office | NA |
| SY88927VZG | Contact Your Local Sales Office | NA |
| SY88952LMG | Contact Your Local Sales Office | NA |
| SY88973BLMG | Contact Your Local Sales Office | NA |
| SY88973BLMG-TR | Contact Your Local Sales Office | NA |
| SY88973VEY | Contact Your Local Sales Office | NA |
| SY88973VEY-TR | Contact Your Local Sales Office | NA |
| SY88973VMG | Contact Your Local Sales Office | NA |
| SY88973VMG-TR | Contact Your Local Sales Office | NA |
| SY88993VKG | SY88993AVKG | Drop-in Replacement Contact Your Local Sales Office |
| SY88993VKG-TR | SY88993AVKG | Drop-in Replacement Contact Your Local Sales Office |
| SY89206VMG-TR | Contact Your Local Sales Office | NA |
| SY89208VMG-TR | Contact Your Local Sales Office | NA |
| SY89218UHY | Contact Your Local Sales Office | NA |
| SY89221UHY | Contact Your Local Sales Office | NA |
| SY89223LMG-TR | Contact Your Local Sales Office | NA |
| SY89229UMG | Contact Your Local Sales Office | NA |

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|--|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY89229UMG-TR | Contact Your Local Sales Office | NA |
| SY89231UMG | Contact Your Local Sales Office | NA |
| SY89231UMG-TR | Contact Your Local Sales Office | NA |
| SY89297UMG | SY89295UMG SY89295UMG-TR SY89295UTG SY89295UTG-TR | FUNCTIONAL Replacement |
| | | Contact Your Local Sales Office |
| SY89297UMG-TR | SY89296UMG SY89296UMG-TR SY89296UTG SY89296UTG-TR | FUNCTIONAL Replacement |
| | | Contact Your Local Sales Office |
| SY89297UMH | SY89296UTG SY89296UTG-TR SY55856UHG SY100EP196VTG SY100EP196VTG-TR | FUNCTIONAL Replacement |
| | | Contact Your Local Sales Office |
| SY89306VMG-TR | Contact Your Local Sales Office | NA |
| SY89307VMG-TR | Contact Your Local Sales Office | NA |
| SY89316VMG-TR | Contact Your Local Sales Office | NA |
| SY89325VMG-TR | Contact Your Local Sales Office | NA |
| SY89420VJZ | Contact Your Local Sales Office | NA |
| SY89420VJZ-TR | Contact Your Local Sales Office | NA |
| SY89421VZH | Contact Your Local Sales Office | NA |
| SY89421VZH-TR | Contact Your Local Sales Office | NA |
| SY89429AJZ | Contact Your Local Sales Office | NA |
| SY89429AJZ-TR | Contact Your Local Sales Office | NA |
| SY89429AZH | Contact Your Local Sales Office | NA |
| SY89429AZH-TR | Contact Your Local Sales Office | NA |
| SY89429VJZ | Contact Your Local Sales Office | NA |
| SY89429VJZ-TR | Contact Your Local Sales Office | NA |
| SY89429VZH | Contact Your Local Sales Office | NA |
| SY89429VZH-TR | Contact Your Local Sales Office | NA |
| SY89430VJZ | Contact Your Local Sales Office | NA |
| SY89430VJZ-TR | Contact Your Local Sales Office | NA |
| SY89430VZH | Contact Your Local Sales Office | NA |
| SY89430VZH-TR | Contact Your Local Sales Office | NA |
| SY89531LHZ | Contact Your Local Sales Office | NA |
| SY89531LHZ-TR | Contact Your Local Sales Office | NA |

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|---|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY89532LHH | Contact Your Local Sales Office | NA |
| SY89532LHH-TR | Contact Your Local Sales Office | NA |
| SY89532LHZ | Contact Your Local Sales Office | NA |
| SY89532LHZ-TR | Contact Your Local Sales Office | NA |
| SY89534LHZ | Contact Your Local Sales Office | NA |
| SY89534LHZ-TR | Contact Your Local Sales Office | NA |
| SY89538LHY | Contact Your Local Sales Office | NA |
| SY89538LHY-TR | Contact Your Local Sales Office | NA |
| SY89538LHZ | Contact Your Local Sales Office | NA |
| SY89538LHZ-TR | Contact Your Local Sales Office | NA |
| SY89542UMG | Contact Your Local Sales Office | NA |
| SY89542UMG-TR | Contact Your Local Sales Office | NA |
| SY89546UMG | Contact Your Local Sales Office | NA |
| SY89610LMG | Contact Your Local Sales Office | NA |
| SY89610LMG-TR | Contact Your Local Sales Office | NA |
| SY897132LKY | Contact Your Local Sales Office | NA |
| SY897132LKY-TR | Contact Your Local Sales Office | NA |
| SY89808LTG | Contact Your Local Sales Office | NA |
| SY89808LTG-TR | Contact Your Local Sales Office | NA |
| SY89809LTH | Contact Your Local Sales Office | NA |
| SY89809LTH-TR | Contact Your Local Sales Office | NA |
| SY89823LHY | Contact Your Local Sales Office | NA |
| SY89823LHY-TR | Contact Your Local Sales Office | NA |
| SY89824LHZ | Contact Your Local Sales Office | NA |
| SY89824LHZ-TR | Contact Your Local Sales Office | NA |
| SY89827LHY | Contact Your Local Sales Office | NA |
| SY89842UMG | Contact Your Local Sales Office | NA |
| SY89842UMG-TR | Contact Your Local Sales Office | NA |
| SY89845UMG | Contact Your Local Sales Office | NA |
| SY89852UMG | Contact Your Local Sales Office | NA |
| SY89852UMG-TR | Contact Your Local Sales Office | NA |
| SY898531LTZ | Contact Your Local Sales Office | NA |
| SY898531LTZ-TR | Contact Your Local Sales Office | NA |
| SY898535LKY | Contact Your Local Sales Office | NA |

JAON-02ILOD785 - End of Life (EOL) of various Micrel products that will not be transferred at Microchip Fabrication sites using 8 inch wafers.

Affected Catalog Part Numbers (CPN)

| PCN_JAON-02ILOD785 | | |
|-------------------------------|---|---|
| EOL Catalog Part Number (CPN) | Recommended Replacement | Notes About the Recommended Replacement |
| SY898535LKY-TR | Contact Your Local Sales Office | NA |
| SY89859UMY | Contact Your Local Sales Office | NA |
| SY89859UMY-TR | Contact Your Local Sales Office | NA |