

**1 Products affected**

| Product hierarchy no. * |     |      |            | Part no.       | SBU                | Type / Description | Customer part no. |
|-------------------------|-----|------|------------|----------------|--------------------|--------------------|-------------------|
| SBU   PG                | PGU | Type |            |                |                    |                    |                   |
| 02                      | 005 | 016  | 0000001202 | See list below | Power Entry Module | 1062               |                   |
|                         |     |      |            |                |                    |                    |                   |

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

| List of part numbers affected |           |           |           |           |
|-------------------------------|-----------|-----------|-----------|-----------|
| 4304.6010                     | 4304.6016 | 4304.6021 | 4304.6145 | 4304.6222 |
| 4304.6011                     | 4304.6017 | 4304.6128 | 4304.6151 | 4304.6320 |
| 4304.6012                     | 4304.6018 | 4304.6135 | 4304.6154 | 4304.6328 |
| 4304.6013                     | 4304.6019 | 4304.6136 | 4304.6165 |           |
| 4304.6014                     | 4304.6020 | 4304.6138 | 4304.6180 |           |

**2 Type of change**

New packaging style


**3 Detailed description of change**

New cardboard box with compartments, new outer dimensions 385x285x55mm.

Old cardboard box



New cardboard box with compartments



**4 Reason of change**

Improved packaging to prevent scratches or other damage.

| 1062          |            |              |             |                  | 0118.2281 |        |
|---------------|------------|--------------|-------------|------------------|-----------|--------|
| creation date | created by | release date | released by | notification no. | revision  | page   |
| 2015-04-16    | huberth    | 2015-08-10   | huberth     |                  |           | 1 of 2 |

## 5 Release date

The change will be rolled-out starting ww 35/2015 and lasts approx. 6 months depending on the variant.

## 6 Impact of change and recommended action

Form: Cardboard box with new outer dimensions 385x285x55mm (WxDxH)  
Power Entry Module itself is unchanged  
Fit: No There are no dimensional changes  
Function: No This is a non-functional change  
Production Site: No There is no change of the production site  
Product Label: No There is no change on the label

## 7 Reference Documents / Attachments

| Kind of document                | Document number | Remarks |
|---------------------------------|-----------------|---------|
| <a href="#">Data Sheet 1062</a> |                 |         |
|                                 |                 |         |

|               |            |              |             |                  |                  |        |
|---------------|------------|--------------|-------------|------------------|------------------|--------|
| <b>1062</b>   |            |              |             |                  | <b>0118.2281</b> |        |
| creation date | created by | release date | released by | notification no. | revision         | page   |
| 2015-04-16    | huberth    | 2015-08-10   | huberth     |                  |                  | 2 of 2 |