



Eaton
Electronics Division
5735 W. Las Positas Blvd #100
Pleasanton, CA 94588
www.eaton.com/electronics

Product Change Notice

PCN#: EE-PCN19018
11/15/2019

CLASSIFICATION OF CHANGE:

End of Life (EOL)

DESCRIPTION OF CHANGE:

Certain part numbers for HHB and HFB in-line fuseholders have reached end of life.

REASON FOR CHANGE:

To rationalize duplicate part numbers consisting of the same construction for both HHB and HFB part families.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. Each direct replacement has the same fit, form and function as the EOL product.

PARTS FAMILIES AFFECTED:

EOL Catalog Number	Direct Replacement	Direct Replacement UPC
HHB	HHB-R	051712659369
BK/HHB	BK/HHB-R	051712658355
HFB	HFB-R	051712659352
BK/HFB	BK/HFB-R	051712658348

TIME SCHEDULE:

Last Time Buy Date: January 31, 2019
Last Time Shipment Date: March 31, 2019

SAMPLE AVAILABILITY:

Available upon request

QUALIFICATION DATA:

Available upon request

ISSUED BY:

Nick Stone
Global Product Line Manager – Circuit Protection

CONTACT INFORMATION:

For questions or comments, please contact <https://www.eaton.com/content/eaton/us/en-us/products/electronic-components/contact-us.html>