TOSHIBA

To: DigiKey

April 2020

Please be informed Toshiba has announced discontinuation on the following product(s) in April 2020. Our sales records indicate you have purchased the following product(s) from Toshiba America Electronic Components in the past.

Products

Item No	Generic PN	Discontinued	Last Time Buy	Last Shipment	Substitution	Replacement PN	Reason	Remarks
DF5A3.6FU(TE85L,F)	DF5A3.6FU(TE85L,F)	Apr'20	6/30/2021	9/30/2021	3	DF5A5.6FU(TE85L,F)	Integration of products	
DF3A3.6FV(TPL3,Z)	DF3A3.6FV(TPL3,Z)	Apr'20	6/30/2021	9/30/2021	2	DF3A5.6FV,L3F	Integration of products	
DF5A3.3JE,LM(B	DF5A3.3JE,LM	Apr'20	6/30/2021	9/30/2021	2	DF5A5.6JE,LM	Integration of products	
DF2B6.8AFS,L3M(B	DF2B6.8AFS,L3M	Apr'20	6/30/2021	9/30/2021	1	DF2B7AFS,L3M	Version Up	
DF3A3.3FU(TE85L,F)	DF3A3.3FU(TE85L,F)	Apr'20	6/30/2021	9/30/2021	2	DF3A5.6FU(TE85L,F)	Integration of products	
DF3A3.3FU(TE85L,F)	DF3A3.3FU(TE85L,F)	Apr'20	6/30/2021	9/30/2021	2	DF3A5.6FU(TE85L,F)	Integration of products	

Last Time Buy (LTB) Option

Toshiba will support last time buy (LTB) orders received on or before the dates listed above (LTB Date). Last time buy orders for all affected products must be in place in total by LTB Date. Deliveries will be scheduled and advised accordingly after receipt of LTB orders. However, unforeseen circumstances might prevent Toshiba to support partially or fully on LTB orders. If such event occurs, we will notify you of our best support plan as soon as possible. Thank you for your understanding. Should you have any questions, please contact your sales representative.

Best Regards,

Logic Device, Discrete Business Unit

Toshiba America Electronic Components, Inc.

TOSHIBA

Substitution Level**

- 0 = No replacement
- 1 =Package and characteristics are mostly same or better, not necessary to change other circuit to replace.
- 2 = Package and characteristics are mostly same or better, but some modification of the other circuit is necessary.
- 3 = Characteristics are same or better, but package/pin arrangement are different, so the other circuit modification is necessary.
- 4 = Other reason