

PRODUCT CHANGE NOTIFICATION

PCN#: CABLE COPPER, FIBER CABLE AND CONNECTORS **20190410-008**

ISSUE DATE: 10-Apr-19

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

Panduit part number FVFLY, a visual fault locator for fiber optics, is being discontinued due to declining sales and discontinuation of the product from the original equipment manufacturer. There will be not be a Pandit replacement number.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2019	4	10
Old product discontinuation date*	2019	4	10

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.