





# PCN - 09 123

Issue Date: September 03 2009

<b>Product Name:</b>	Millipacs® Receptacle series Bottom Shield		
	PNs start with HM2LS*, Pls refer to enclosed sheet (including but not limited to the Part numbers)		
<b>Product Manager:</b>	Talee Luo		
<b>Subject:</b>	Product Change Notification		
<b>Distribution:</b>	Active and Contract Customers		
<b>Type of Change:</b>	Manufacturing Process Change		
<b>Change Description:</b>	<p>Modify the holes shape of the Millipacs Receptacle Connector Bottom shielding as shown in picture. This improvement will provide more clearance between the contact terminal tails and metallic shields.</p>   <p style="text-align: center;"> <span style="margin-right: 100px;">Current</span> <span>Improved</span> </p>		
<b>Reason for Change:</b>	FCI has improved application friendliness of the Millipacs Bottom shield through expanded hole size. Samples are available on request and this change will be implemented for entire Millipacs receptacle series bottom shielding		
<b>Affected Parts:</b>	Please refer attached affected part list		
<b>Effective Date of Change:</b>	December	04	2009
<b>Last Time Buy Date:</b>	N/A	N/A	N/A
<b>Last Disty Return Date:</b>	N/A	N/A	N/A
<b>Datasheet Attached?</b>	No		
<b>Qual/Test Data Attached?</b>	No		
<b>Samples Availability Date:</b>	September	03	2009
<b>Available Alternatives?</b>	N/A <i>Part numbers will not change.</i>		
<b>Questions?</b>	<p>Contact your local FCI Representative</p> <p>Talee Luo</p> <p>8676988669299 / luota@fci.com</p>		