

TE Connectivity

Product Change Notification: P-20-019925 PCN Date: 28-OCT-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Relaissockel

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from Supplier Germany to Supplier Portugal and Supplier Netherland: PN 4-1414915-3,
4-1414915-4 Dear customer, we received a discontinuation information from our supplier Merkon Industrieteile for the following sockets: 2-1904045-4 / V23333Z0002A041-EV-100, 4-1904045-4 / V23333Z0002B049-EV-100, 4-1904045-7 / V23333Z0002B049-EV-441. Due to that we will transfer the production of these sockets.

Reason for Changes:

Dear Customer, we hereby inform you about a transfer of tools and/or processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery. Upon request, a PPAP Level 2 will be available if it concerns a transfer of a tool which produces a finished TE-product. A PPAP Level 1 will be available if it concerns a component of a TE-product, where the production location of the finished TE-product remains unchanged. If you require such a PPAP, please notify the responsible TE Sales Contact within 14 calendar days after receipt of this PCN

Estimated Dates:

201111111111111111111111111111111111111	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	05-APR-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-1904045-4	NO			"3 334 485 041", "V23333-Z0002-A041"			
2-1904045-7	NO			"3 334 485 049", "V23333-Z0002-B049"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-1904045-4	NO			"3 334 485 041", "V23333-Z0002-A041"			
2-1904045-7	NO			"3 334 485 049", "V23333-Z0002-B049"			

Part Number(s) being Modified:

	Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
I	2-1904045-4	NO			"3 334 485 041",			
ŀ	2-1904045-4	NO			"V23333-Z0002-A041"			