

# Product Discontinuation

2015-07-31

**OS-PD-2015-027**

Last order:	15.09.2015
Last delivery:	30.06.2016

Reason: Chips no more available due to discontinuation from chip supplier

**Please direct your inquiry to your local Sales office.**

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Brand	Device	Ordering Code	Function	Brand
SFH 5140F	Q62702P5112	Detector	Molded Sidelooker	under consideration			
SFH 5140F-1/3	Q65110A9617	Detector	Molded Sidelooker	under consideration			
SFH 5440	Q65110A1212	Detector	SmartDIL	under consideration			
SFH 9245	Q65111A3174	Detector	RLS	under consideration			