

PRODUCT OBSOLESCENCE NOTICE

1 September 2010

Dear Customer,

Murata Power Solutions (MPS) hereby gives official notification that the following product(s) you may have purchased from us are now obsolete. Unfortunately, we are not offering a Last-Time-Buy (LTB) due to the obsolescence of a major component that was used in this DC/DC converter.

Product Part Number	Recommended Alternative
HL01R05D15ZC	No Recommendation
HL01R05S05YC	No Recommendation
HL01R05S05ZC	No Recommendation
HL01R05S12YC	No Recommendation
HL01R24D05ZC	No Recommendation
HL01R24D12YC	No Recommendation
HL01R24D15YC	No Recommendation
HL01R24S05YC	No Recommendation

Should you have any questions or concerns please contact your local MPS Representative, Distributor, or Regional Sales Manager at <http://www.murata-ps.com/offices.html>.