

Product Change Notice

PCN#:EE-PCN20002


April 1, 2020

CLASSIFICATION OF CHANGE:

Shrink Sleeve Marking

DESCRIPTION OF CHANGE:


Change negative lead indicator on all supercapacitor packs. New stripe will be visible from the side and from the ends at all angles.



Existing



Stripe aligned with negative lead



New

REASON FOR CHANGE:

Improve customer auto placement machines optical read rates for proper orientation.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

None

PARTS FAMILIES AFFECTED:

PB family
PHB family
PHV family

TIME SCHEDULE:

Start Shipment
Date: June 15th, 2020

SAMPLE AVAILABILITY:

Not applicable

QUALIFICATION DATA:

Not applicable

ISSUED BY:

Product Manager: Jason Lee

CONTACT INFORMATION:

For questions or comments, please contact <https://www.eaton.com/content/eaton/us/en-us/products/electronic-components/contact-us.html>