		April 21	, 2022	PCN Number :	511593		
Reason for Change :		Change	Supplier				
Description of Change :			Supplier change due to discontinuation of the previous supplier, as a result the part will be produced by new enlisted supplier.				
ssessment of Ch	ange :	First Art	First Article Inspection				
lanned Impleme	ntation Date :	October	October 24, 2022				
ample Availabili	ty Date:	October	October 05, 2022				
nternal Molex Qu	alification Date :	October	October 05, 2022				
ast date to reque	est Samples by Cu	stomer: Apr	ril 30, 2022				
raceability Code	Markings / Date :	No spec	No special marking on the product or packaging				
			32 ±0.38 5 ±0.25		3		
2 800 00 00 00 00 00 00 00 00 00 00 00 00		63.					
	Parameter	63.	5 ±0.25	After	5.8 ±0.25		
		63.			5.8 ±0.25		

After Picture

Overview

- As the current supplier has discontinued the supply of the part, the same is now being supplied from another enlisted supplier
- Product fit is being impacted as shown in slide 1
- Please find impacted Product list
- Qualification Reports and samples available upon request after the date shown above

RELEASED

You may address inquires regarding this PCN by clicking on the below link <u>mailto:pcn_coordinator@molex.com?subject=PCN_Notification:511593</u> or contact your Local Sales Engineer.

Note: While responding, please retain "PCN Notification : PCN Notification: 511593 " in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com
 PCN No
 Part List

 511593
 1731130070