



Product Change Notification

TE Connectivity

Product Change Notification: E-16-009203

PCN Date: 25-JUL-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
 TIMER CONTACT (LP) and MQS 1.5 SOCKET CONTACT (LP)

Description of Changes
 Obsolete Loose piece terminals - The following part numbers are being discontinued (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant differences described. Please verify all substitute or alternate part numbers provided are suitable for your specific application. Drawings are available via TE.com.
 Other attachments:
[Cutting Tool 5- 1579002- 8](#)
[LP PN's](#)

Reason for Changes:	
Discontinuance. Discontinuance.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
10-OCT-2016	
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
10-JAN-2017	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
927779-1	YES						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
927779-1	YES						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
927779-1	YES						