

Title of Change:	Updated to PD23900Z - Reactivation of previously discontinued parts.				
Last Time Buy Date:	NA				
Last Ship Date:	NA				
Contact information:	Contact your local onsemi Sales Office or <u>Sungdae.Shin@onsemi.com</u>				
Type of notification:	Customers must notify onsemi (< <u>PCN.Support@onsemi.com</u> >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.				
Description and Purpose	:				
This is to formally inform custom shall be considered active.	ers of the reactivation of devices li	isted in this Notification, that were previously discontinued in PD23900Z. Parts			
For questions or concerns regard	ing this notification, please contact	t your local sales office or customer service representative.			
Additional contacts are:					
Americas:		Europe:			
Tom Siegel (tom.siegel@onsemi.com)		Andrej Tomasik (andrej.tomasik@onsemi.com)			
		a +421 33790 2229			
USA		Slovakia			
Japan:		Asia Pacific:			
Isao Usuki (isao.usuki@onsemi.com)		Stephen Ng (stephen.ng@onsemi.com)			
Japan		China			
List of Affected Parts:		e parts list. Any custom parts affected by this PCN are shown in the customer			
,	N email notification, or on the <u>PCN</u>				

Part Number	Replacement part	Supplier
NFAL5012L5BT	#NONE	#NA
NFAL5012L5B	#NONE	#NA
NFAL3512L5BT	#NONE	#NA
NFAL3512L5B	#NONE	#NA
NFAL2512L5B	#NONE	#NA
NFAL1512L5B	#NONE	#NA



Appendix A: Changed Products

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
NFAL3512L5BT			NA	