


Product Name:	HPL-511 - USB	
	USB+POWER	
Product Manager:	Jimmy Wang	
Subject:	Notification of Change with Immediate Effectivity	
Distribution:	Affected customers	
Type of Change:	Materials Change	
Change Description:	Change the paper tape to acetate tape to protect the wires	
		
Reason for Change:	NCR complained the powerusb cable assembly had short issue ,the root cause is the wire easily hurt by the edge of the shell ,so change the paper tape to acetate tape to protect the wires	
Affected Parts:	10134719-Z0300YYLF;10134777-Z0240YYLF;10133862-Z0120YYLF	
Effective Date of Change:	30 November ,2022	
Last Time Buy Date:		
Earliest Disty Return Date:		
Last Time Shipment Date		
Datasheet Attached?	NA	
Qual/Test Data Attached?	NA	
Samples Availability Date:	07 November ,2022	
Available Alternatives?		
Questions?	<i>Contact your local ACS Representative, or Product Manager</i>	
	<i>Jimmy Wang / Product Manager</i>	
	<i>jimmy.wang@fci.com</i>	

Note:

Customers should contact Product Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .