# **Product / Process Change Notification**



### N° 2018-028-A

Dear Customer,

Please find attached our INFINEON Technologies PCN:

# Silicon Improvement and Data Sheet Update Affecting Product IFX90121EL V50

Important information for your attention:

- Please respond to this PCN by indicating your decision on the approval form, sign it and return to your sales partner before 5<sup>th</sup> July 2018.
- Infineon aligns with the widely-recognized JEDEC STANDARD "JESD46", which stipulates: "Lack of acknowledgement of the PCN within 30 days constitutes acceptance of the change."
- This PCN includes a **Product Discontinuation Notice** (JEDEC STANDARD "JESD48") **on** page 4/4.

Your prompt reply will help Infineon Technologies to assure a smooth and well executed transition. If Infineon does not hear from your side by the due date, we will assume your full acceptance to this proposed change and its implementation.

Your attention and response to this matter is greatly appreciated.

Disclaimer:

If we do not receive any response by the date in the PCN above we consider this as the acceptance of the PCN. After the last order date as stated herein, purchase orders related to the unchanged product(s) cannot be accepted.

In case the customer rejects this PCN this PCN shall be considered a product discontinuation notice (PD).

Infineon Technologies AG Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0 Chairman of the Supervisory Board: Dr. Eckart Sünner Management Board: Dr. Reinhard Ploss (CEO), Dominik Asam, Dr. Helmut Gassel, Jochen Hanebeck Registered Office: Neubiberg Commercial Register Amtsgericht München HRB 126492

# Product / Process Change Notification



### N° 2018-028-A

► **Products affected:** Please refer to attached affected product list 1\_cip18028\_a

### Detailed Change Information:

Subject:	Silicon improvement, and data sheet update affecting product IFX90121EL V50 Device robustness was improved at very fast load step behavior (e.g. load step 100µA -> 300mA or higher, in less than 1µs). SYNC parameter (min high/low time) within the datasheet was updated to reflect the most relevant application conditions.					
Reason:						
Description:	<u>Old</u>	New				
Silicon Redesign	Triggered by a load step (i.e. increase of output current) the product may stay in PFM mode with consequence of decreasing output voltage.	<ul> <li>The redesign now ensures that after a load step the device will switch into the PWM mode as expected.</li> </ul>				
SYNC min high/low time	■ 25µs	■ 50µs				
Data Sheet	Rev. 1.0	Rev. 1.1				
Product Identification:	Traceability is ensured by lot number. SP number and ordering part number are different					
Impact of Change:	No changes in quality, reliability, and manufacturability of the products. Change in function is considered as uncritical and does not affect data sheet parameters. Datasheet update not considered to be application relevant.					
Attachments:	1_cip18028_A: Affected product list 4_cip18028_A: Data Sheet Update					

# **Product / Process Change Notification**



#### N° 2018-028-A

#### ► Time Schedule: Final qualification report: Available on request Available on request

- First samples available:
- Intended start of delivery:

#### Refer to page 4/4:

Last order date of unchanged product:

01-January-2019

August 2018 or earlier after customer release

Last delivery date of unchanged product: 01-July-2019

If you have any questions, please do not hesitate to contact your local Sales office.



## referring to PCN N° 2018-028-A

Last order date of unchanged product: 2019-01-01

Last delivery date of unchanged product: 2019-07-01

DISCONTINUED			NEW (REPLACEMENT)				
Sales name	SP number	OPN	Package	Sales name	SP number	OPN	Package
IFX90121EL V50	SP001118296	IFX90121ELV50XUMA1	PG-SSOP-14	IFX90121EL V50	SP001779966	IFX90121ELV50XUMA2	PG-SSOP-14