



# Product Change Notification

## TE Connectivity

Product Change Notification: P-20-019425

PCN Date: 04-AUG-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

HCR150 Relays

**Description of Changes**

Second source supplier for raw material used on iron components. This vendor already supplies the same raw material for other product families.

**Other attachments:**

[Presentation](#)

**Reason for Changes:**

Product improvement. The current Magnetic Iron (RFe) suppliers have revealed difficulties guarantying the volumes/lead times required by TE. To protect and assure TE capability to meet customer demand, we have approved an alternative source supplier of RFe acc. TEC-100-2220 that can be used as alternative.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	01-JAN-2021
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1414476-0</a>	NO						
<a href="#">1-1414632-0</a>	NO						
<a href="#">1393315-2</a>	NO			"V23132A2001A200"			
<a href="#">1393315-9</a>	NO			"V23132B2002A200"			
<a href="#">1416010-1</a>	NO			"V23132-A2001-B200"			
<a href="#">2-1414939-2</a>	NO			"V23132A2001B200-EV-USBX"			
<a href="#">5-1414968-1</a>	NO			"V23132B2002B200-EV-USBX"			
<a href="#">9-1415001-5</a>	NO			"CZ1474-000"			

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1414476-0</a>	NO						
<a href="#">1-1414632-0</a>	NO						
<a href="#">1393315-2</a>	NO			"V23132A2001A200"			
<a href="#">1393315-9</a>	NO			"V23132B2002A200"			
<a href="#">1416010-1</a>	NO			"V23132-A2001-B200"			
<a href="#">2-1414939-2</a>	NO			"V23132A2001B200-EV-USBX"			
<a href="#">5-1414968-1</a>	NO			"V23132B2002B200-EV-USBX"			
<a href="#">9-1415001-5</a>	NO			"CZ1474-000"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1414476-0</a>	NO						
<a href="#">1393315-2</a>	NO			"V23132A2001A200"			
<a href="#">1393315-9</a>	NO			"V23132B2002A200"			
<a href="#">1416010-1</a>	NO			"V23132-A2001-B200"			
<a href="#">2-1414939-2</a>	NO			"V23132A2001B200-EV-USBX"			
<a href="#">9-1415001-5</a>	NO			"CZ1474-000"			