soberton inc.

Soberton 4M Change Notice

Date May 28,	2018					
Change type	Change type Material / Specification Change Equipment change Process change Man change					
(Product name)	BUZZER PT-1704			(Affected date of the change)	2018.5.28	
(Reason of change):						
Due to the mold of cover is damaged and out of order. The cover is the same size but the						
appearance is slightly different than before.						
The changes are as below;						
(Before ch	(Before change): (A			(After change):		
Cover: No ring around the hole Cover: A more ring around the hole Top view					ne hole	
Cover: Has	Cover: Has gap on cover			Cover: No gap on cover		
	Button vie	W	Button view			
These changes will not caused any impact on the use and function of the component.						
(A	(Approved by) (Check		(Prepare		repared by)	
	Eric Yu		ting		Tina	
					QR-QA-075A	