

## **Global Change Notification (GCN)**

Product Family	MX150	10650323
		GCN Number

Series 33482-12xx, 33482-13xx & 33482-16xx,

33482-12xx, 33482-13xx & 33482-16xx, 33482-17xx

August 12, 2014


Date Issued

Reason For Change

New, Modified, Or Replacement Tooling

Change Description

The purpose of this letter is to inform you that the tools which make the Mat Seals used in Blade Connectors in finished goods 33482-12xx, 33482-13xx & 33482-16xx, 33482-17xx have reached end of life and are now being replaced. The color will remain "Rust Red". All other components in the finished good will remain the same.



Part Numbers Affected	Please refer to CustomerPartList.csv attached t	o e-mail message.
Reason For Short Notice Exception	New Capacity	
Assessment Of Change (How Product Will Be Qualified & Validated)	validation testing	
Internal Molex Qualification Date (Planned Date Information Available)	September 15, 2014	
Sample Availability Date (Changed Part)	September 15, 2014	
Date of Implementation	September 15, 2014	
Method of Identifying Change	added cavity numbers	
Recommended Replacement Parts	NA	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number	
Sales Engineer	Please refer to e-mail message for your local sales engineer.			
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416	
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751	
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472	
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352	

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com