


Chandler, April 8th, 2021

USB CONNECTOR CHANGE NOTICE

1002-014-01000 with a date code AFTER 20/02 does not come with the back portion of the shell.

Shown in the drawing uploaded:



Please review comparison drawing and the step file for design, dimensional and tolerance changes.

Regards,

H. Meyer
CnC Tech

#