

NO: CON-021 **PRODUCT:** G79 Terminal Block Cables
DATE: September 2016 **TYPE:** Discontinuation Notice

G79 Series Connector Cables for Terminal Blocks Discontinued; Replace with XW2Z-R Series Cables

Discontinuation date: September, 2016

Affected Parts



Product discontinuation	Recommended replacement	Product discontinuation	Recommended replacement
G79-Y50C	XW2Z-RY50C	G79-O300C-275	XW2Z-RO300C-275
G79-Y100C	XW2Z-RY100C	G79-O500C-475	XW2Z-RO500C-475
G79-Y150C	XW2Z-RY150C	G79-O1000C-975	XW2Z-RO1000C-975
G79-Y200C	XW2Z-RY200C	G79-150C-125-100	XW2Z-R150C-125-100
G79-Y300C	XW2Z-RY300C	G79-200C-175-150	XW2Z-R200C-175-150
G79-Y500C	XW2Z-RY500C	G79-300C-275-250	XW2Z-R300C-275-250
G79-Y700C	XW2Z-RY700C	G79-500C-475-450	XW2Z-R500C-475-450
G79-Y1000C	XW2Z-RY1000C	G79-755C-850-943	No recommended replacement
G79-A200C	XW2Z-RA200C	G79-1000C-975-950	XW2Z-R1000C-975-950
G79-A500C	XW2Z-RA500C	G79-I25C	XW2Z-RI25C
G79-A800C	XW2Z-RA800C	G79-I50C	XW2Z-RI50C
G79-50C	XW2Z-R50C	G79-O25C	XW2Z-RO25C
G79-100C	XW2Z-R100C	G79-O50C	XW2Z-RO50C
G79-150C	XW2Z-R150C	G79-I50-25-D1	XW2Z-RI50-25-D1
G79-200C	XW2Z-R200C	G79-I75-50-D1	XW2Z-RI75-50-D1
G79-300C	XW2Z-R300C	G79-M50-25-D1	XW2Z-RM50-25-D1
G79-500C	XW2Z-R500C	G79-M75-50-D1	XW2Z-RM75-50-D1
G79-800C	XW2Z-R800C	G79-O50-25-D1	XW2Z-RO50-25-D1
G79-1000C	XW2Z-R1000C	G79-O75-50-D1	XW2Z-RO75-50-D1
G79-I100C-75	XW2Z-RI100C-75	G79-A200C-D1	XW2Z-RA200C-D1
G79-I150C-100	XW2Z-RI150C-100	G79-A500C-D1	XW2Z-RA500C-D1
G79-I150C-125	XW2Z-RI150C-125	G79-Y100C-D1	XW2Z-RY100C-D1
G79-I200C-175	XW2Z-RI200C-175	G79-Y200C-D1	XW2Z-RY200C-D1
G79-I300C-275	XW2Z-RI300C-275	G79-Y500C-D1	XW2Z-RY500C-D1
G79-I500C-475	XW2Z-RI500C-475	G79-I50-25-D2	XW2Z-RI50-25-D2
G79-I1000C-975	XW2Z-RI1000C-975	G79-I75-50-D2	XW2Z-RI75-50-D2
G79-O100C-75	XW2Z-RO100C-75	G79-M50-25-D2	XW2Z-RM50-25-D2
G79-O150C-100	XW2Z-RO150C-100	G79-M75-50-D2	XW2Z-RM75-50-D2
G79-O150C-125	XW2Z-RO150C-125	G79-I100C-75-MN	XW2Z-RI100C-75-MN
G79-O200C-150	XW2Z-RO200C-150	G79-I150C-125-MN	XW2Z-RI150C-125-MN

Product discontinuation	Recommended replacement	Product discontinuation	Recommended replacement
G79-O200C-175	XW2Z-RO200C-175	G79-I175C-150-MN	XW2Z-RI175C-150-MN
G79-I200C-175-MN	XW2Z-RI200C-175-MN	G79-I350C-300-YE	No recommended replacement
G79-I300C-275-MN	XW2Z-RI300C-275-MN	G79-I350C-325-YE	No recommended replacement
G79-I500C-475-MN	XW2Z-RI500C-475-MN	G79-O250C-225-YE	No recommended replacement
G79-I1000C-975-MN	XW2Z-RI1000C-975-MN	G79-O300C-250-YE	No recommended replacement
G79-O100C-75-MN	XW2Z-RO100C-75-MN	G79-O350C-300-YE	No recommended replacement
G79-O150C-75-MN	XW2Z-RO150C-75-MN	G79-O400C-350-YE	No recommended replacement
G79-O150C-125-MN	XW2Z-RO150C-125-MN	G79-200C-175-ES1	No recommended replacement
G79-O175C-150-MN	XW2Z-RO175C-150-MN	G79-200C-ES1	No recommended replacement
G79-O200C-150-MN	XW2Z-RO200C-150-MN	G79-150C-125-100-OE	No recommended replacement
G79-O200C-175-MN	XW2Z-RO200C-175-MN	G79-200C-175-150-OE	No recommended replacement
G79-O300C-175-MN 3M	XW2Z-RO300C-175-MN	G79-300C-275-250-OE	No recommended replacement
G79-O300C-275-MN	XW2Z-RO300C-275-MN	G79-I350C-350S	No recommended replacement
G79-O1000C-975-MN	XW2Z-RO1000C-975-MN	G79-B200C	No recommended replacement
		G79-B400C	No recommended replacement

See the detail of differences below.

Detail of Differences

Body Color

Product discontinuation Model G79-□ series	Recommended replacement Model XW2Z-R□ series
<p>Wire color : Gray</p> 	<p>Wire color : Black</p> 

Specifications and prices in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.