

PRODUCT DISCONTINUATION

#PD-DCT-RUWS-11

Business Unit	Product Line Code	Type of Change	Action	Date of issue
DCT	245	Discontinuation	Notify Distributors and Field	02/24/2011

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

The packaging width for the smaller position PTSM product has been changed from R44 to R24. The smaller tape width ensures proper stabilization of the product within the packaging.

Warranty Information:

N/A

Stock Status

Can existing stock still be used? N

Is mixture of stock acceptable? N

Transaction Dates:

Last Buy from Phoenix Contact: 01/31/2011

Last Scheduled Ship from Phoenix Contact: 04/30/2011

PRODUCT DISCONTINUATION

Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

ANDREW BOGACZYK
 (800)888-7388x3075
 abogaczyk@phoenixcon.com

Thank you,



Steve Barber, Product Marketing Manager

Discontinued Part#	Type Description	Replacement Part#	Type Description
1771020	PTSM 0,5/ 2-2,5-H SMD R44	1702473	PTSM 0,5/ 2-2,5-H SMD R24
1771046	PTSM 0,5/ 4-2,5-H SMD R44	1702474	PTSM 0,5/ 4-2,5-H SMD R24