

## PRODUCT DISCONTINUATION NOTIFICATION

PDN No.: USA2011 / 008 Issue Date: 10/11/2011

IXYS Corporation has found it necessary to discontinue certain products. This notification is to inform you that this change may affect your products. If you have any comments on the discontinuation please fill out and return the attached customer response form on Page 2 within 30 days of the PDN Issue date.

Page 2 within 30 days	S OI THE PUN IS	sue uale.		
REASON FOR DISCONTI	NUATION:			
New Technology availab	le			
PDN TIME LINE:				
LAST TIME ORDER DATE: Nov. 30 2011				
LAST TIME DELIVERY DATE: Mar. 31 2012				
IXYS Part No.:	Product Type:	Manufactured Since:	Recommended Replacement:	
	, , , , , , , , , , , , , , , , , , ,		F	

IXYS Part No.:	Product Type:	Manufactured Since:	Recommended Replacement:
IXFH40N50Q2	Q2 HiPerFET	April 2003	IXFH44N50Q3
IXFK40N50Q2	Q2 HiPerFET	April 2003	IXFK44N50Q3
IXFR40N50Q2	Q2 HiPerFET	April 2003	IXFR44N50Q3
Link to Datasheets			Link to Datasheets

## PDN CREATED/UPDATED

DATE: 11/4/11

ORIGINATOR: V. Tsukanov; VP R&D Power MOS Products

REVIEWED BY: Gordon Rosete, Dir QA-QC

IF 0266 REV. B



## PRODUCT DISCONTINUATION NOTIFICATION

PDN No.: USA2011 / 008	Issue Date: 10/11/2011
CUSTOMER RESPONSE:	
Company:	Date:
Name:	Position:
Phone/Fax/e-mail:	
Comments:	

**RETURN TO**: IXYS CORPORATION

JOSIE VELACION QA/QC DEPT. HEAD

1590 BUCKEYE DRIVE, MILPITAS, CA 95035-7418

PHONE: +1-408-457-9085 E-MAIL: <u>i.velacion@ixys.net</u>

IF 0266 REV. B

Page 2 of 2