

IloT Product Change Notice

This change will be applied on the BB-485FPP. If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.

1. Reason for the Change: Standardize parts procurement for the terminal block

2. Affected Products: BB-485FPP

3. Impact on Application:

Item	Impact
Impact on Mechanical Design	Yes
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on System Certifications	No
Physical Outlook Change	Yes
Ordering P/N Change	No
Cut-in Implement	Component Running Change

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference Mechanical Design Difference	Reason
BB-485FPP	TL200V-02P-MC	EK500V-02P(S)-BK	Terminal Block	Customers may notice a slightly different shade of grey / black. The new terminal block is 1.3 mm taller.	Procurement lead time and standardization.

5. Implementation & Schedule of the Change(s):

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
BB-485FPP	ECOM-182995	11/30/2021	Running Change	Replace terminal block TB1 p/n 1652007865-01 with new part 1652008294-01 due to procurement issues.

**Note: Cut-in progress depends on factory production schedule. Mixed inventory can be expected.*

Contact Windows

PM	Brian Foster / brian.foster@advantech.com
AE	