

TE Connectivity

Product Change Notification: P-18-016642 PCN Date: 27-NOV-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
MQS/MCP HYB 22P CAP ASSY

Description of Changes

TE Connectivity Brazil would like to inform about the local production of MQS/MCP HYB 22P CAP ASSY listed in this PCN.

Reason for Changes:

Dear Customer, we hereby inform you about local production of MQS/MCP HYB 22P CAP ASSY listed at this PCN. Brazil Production is to better meet customer demands and improve our delivery. The Brazil Manufacturing location operates under certified quality management system in accordance with standard concerned automotive requirements. A TE internal realease test based on relevant part specifications will be executed before delivery. PPAP will be submitted before SOP for all customers which had required.

Estimated Dates:

Estillated Dates.	ateu Dates.				
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):				
	15-JAN-2019				
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):				
	No Mixed Shipments				

Part Number(s) being Modified:

Part Number	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
1897540-2	NO						

Part Number(s) being Modified:

Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
1897540-2	NO						

Part Number(s) being Modified:

Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
1897540-2	NO						