

TE Connectivity

Product Change Notification: E-18-019813-C PCN Date: 08-DEC-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

MCP 1.5mm 5p MAIN plug HSG (1897234) // MCP 1.5mm 5p sub plug HSG (1897235)

Description of Changes

PLUG & CAP GAP REDUCTION - RIB ADDITION

Reason for Cancellation:

CUSTOMER REQUEST THE CHANGE CANCEL

Part Number(s) being Modified:

Part Number	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
1897208-1	NO						

Part Number(s) being Modified:

Part	Part Discontinued per PCN	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number		Drawing	Number	Number(s)	Number	Number(s)	Difference
1897208-1	NO						

Part Number(s) being Modified:

Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
1897208-1	NO						