Light is OSRAM



22.12.2015

## OS-RIDC-2015-001 Replacement in Due Course

Objective	Replacement i	n Due Course					
Background		OSRAM OS has started the replacement process. Please find below the recommended replacements.					
		OSRAM OS expects the end of life ("Not for new design in") within the next 1 - 3 years.					
	Revenue Introdu	R	eplacement NFND PDN due course	nuation			
Replacement in D	ue Course products	Recommended replacement					
Device	Brand	Device	Brand	Availability			
LUW CJSN	CURAMOS 3020	KW DMLN32.SB	SYNIOS P2720	Q3/2016			

LE UW U1A5 05	OSRAM OSTAR	KW HLL531.TE	OSLON Black Flat	Q2/2016
	Headlamp Pro			
LA H9PP	<b>OSLON Black Flat</b>	KR DMLS31.23	SYNIOS P2720	Q65111A6094
LR H9PP	<b>OSLON Black Flat</b>	KR DMLS31.23	SYNIOS P2720	Q65111A6094
LS H9PP	<b>OSLON Black Flat</b>	KS DMLS31.23	SYNIOS P2720	Q65111A6091
LY H9PP	<b>OSLON Black Flat</b>	KY DMLS31.23	SYNIOS P2720	Q65111A6088

## Please direct your inquiry to your local Sales office.

OSRAM Opto Semiconductors GmbH

Head Office:

Leibnizstrasse 4 93055 Regensburg, Germany Phone +49 941 850-5 Fax +49 941 850-1002 www.osram-os.com

