



MICRON_Additional Assembly and Test Sites for 3400 SSDs - Malaysia

PCN: 34341

Published: 2021-10-25

Revision History:

REVISION 1, 2021-12-16: This revision supersedes the original PCN 34341 dated 2021-10-25

This revision is to call out changes to the Method of Identification in the notification below. Due to multiple sites in Malaysia, site indicator will be added in parentheses after the Country of Origin. Example: MNG - Malaysia, MMP - Malaysia (PE), and Hotayi - Malaysia (HO). See attached.

Type: Manufacturing Site - Change or Addition

Description: Micron will be adding assembly and test sites in Penang, Malaysia for 3400 SSD products. This will enable greater flexibility of supply and support for upside opportunities.

Current SSD Assembly and Test Sites:

- MSB — Micron Semiconductor Asia A/T, 990 Bendemeer Road, Singapore 339942, Singapore
- MNG — Micron Memory Malaysia Sdn. Bhd., 1063, Plot 19, Tingkat Perusahaan 6, Prai Industrial Estate, 13600 Prai, Penang, Malaysia
- USI — Universal Scientific Industrial, (Shanghai) Co Ltd, No 1558 Zhang Dong Rd, Shanghai 201203, China

Future Assembly and Test Sites:

- MSB — Micron Semiconductor Asia A/T, 990 Bendemeer Road, Singapore 339942, Singapore
- MNG — Micron Memory Malaysia Sdn. Bhd., 1063, Plot 19, Tingkat Perusahaan 6, Prai Industrial Estate, 13600 Prai, Penang, Malaysia
- USI — Universal Scientific Industrial, (Shanghai) Co Ltd, No 1558 Zhang Dong Rd, Shanghai 201203, China
- **MMP — Micron Memory Malaysia Sdn.Bhd . PMT 779, Lingkaran Cassia Selatan, Taman Perindustrian Batu Kawan, 14110 Bandar Cassia, Seberang Perai Selatan, Pulau Pinang, Malaysia**
- **Hotayi (Assembly and 512GB/1TB only) — Hotayi Electronic (M) Sdn. Bhd. PMT 751, Persiaran Cassia Selatan 1, Taman Perindustrian Batu Kawan, 14100 Bandar Cassia Batu Kawan, Penang, Malaysia**

Sample, Qual Data and Product Availability by Site

	MMP	Hotayi
Qual Data Available	2021-10-27	2021-10-27
Sample Available	2021-11-06	2021-11-06
Product Ship Date	2022-02-04	2022-02-04

Reason: Supply Flexibility/Security

Product Affected: Micron 3400 512GB, 1TB, and 2TB M.2 SSDs (512GB and 1TB only at Hotayi)

Affected Micron Part Number	Recommended Replacement	Customer Part Number
<u>MODULE</u>		
MTFDKBA1T0TFH-1BC15ABYY		557-MTFDKBA1T0TFH-1BC15ABYY-ND
MTFDKBA1T0TFH-1BC1AABYY		557-MTFDKBA1T0TFH-1BC1AABYY-ND
MTFDKBA2T0TFH-1BC15ABYY		557-MTFDKBA2T0TFH-1BC15ABYY-ND
MTFDKBA2T0TFH-1BC1AABYY		557-MTFDKBA2T0TFH-1BC1AABYY-ND
MTFDKBA512TFH-1BC15ABYY		557-MTFDKBA512TFH-1BC15ABYY-ND
MTFDKBA512TFH-1BC1AABYY		557-MTFDKBA512TFH-1BC1AABYY-ND

*Materials that have been ordered are in **bold**.

Method of Identification:	The label will indicate the country of origin (Singapore, Malaysia, China). Due to multiple sites in Malaysia, site indicator will be added in parentheses after the Country of Origin. Example: MNG - Malaysia, MMP - Malaysia (PE), and Hotayi - Malaysia (HO). See attached.
Micron Sites Affected:	All Sites
Sample Available:	2021-11-06
Qual Data Available:	2021-10-27
Product Ship Date:	2022-02-04

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Attachments
