

PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

To: Grayhill Distributors

Date: January 5, 2018

Subject: Obsoleting 76P09

Description:

This Product Advisory Notice is to alert you that Grayhill has obsoleted 76P09

Reason for Change:

Low volume, vendor price & minimum increases

Effective Date:

This has been in process since 2015

Details:

76P09 (Description: Accessory; 9 Position Dip Switch Cover) is no longer available; no suggested replacement.

Action Required:

Remove 76P09 from your pricing system & make a notation that it is obsolete; no longer available.

E-mail: distributor_sales@grayhill.com

Bulletin #XXZ

Page 1 1-5-2018