

## **Global Change Notification (GCN)**

Product Family	SRC	10719332	
		GCN Number	
Series	85084, 93287	September 25, 2015	
		Date Issued	
Reason For Change	Product Component Change		
Change Description	This is to inform you that Molex is changing the back cover on the female SRC assemblies. This change will involve tightening the cores to reduce the permissible angle of terminal insertion.		
CCCCC A LA LA LA LA COCCCCC COCCA LA LA LA LA COCCCCC COCCA LA LA LA LA LA LA LA COCCA LA LA LA LA LA LA COCCA LA COCCA LA			
Before		After	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to	e-mail message.	
Reason For Short Notice Exception	8D Corrective Action Changes		
Assessment Of Change How Product Will Be Qualified & Validated)	This change will have no affect on the function of the product. Report available upon request.		
Internal Molex Qualification Date (Planned Date Information Available)	October 09, 2015		
Sample Availability Date (Changed Part)	October 19, 2015		
Date of Implementation	October 30, 2015		
Method of Identifying Change	Factory order number		
Recommended Replacement Parts	N/A		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com