



September 1, 2022

Discontinuation of Specific Not Recommended for New Designs and Consult Factory Models

Dear Valued Phihong Customer:

Please be advised that effective immediately the below Not Recommended for New Designs, Consult Factory and/or Special Order (MOQ or BTO) models are discontinued. The recommended Phihong replacement models are indicated but please understand that there might not be an available Phihong replacement model for every case.

<u>MODEL NUMER</u>	<u>RECOMMENDED REPLACEMENT MODEL</u>
PSM03A-120-R	AA03A-120A-R
PSAA06A-120L6-R	PSAC12R-060-R + RPA-AB01B-H or PSC15A-060-R
PSAA15W-120L6-R	PPL18W-120
PSAA15W-480L6-R	PPL24W-480
PSAC45W-120-R	PPL65W-120
PSAC45W-240-R	PPL65W-240
PSAC60M-240-R	PPL65U-240 (or PPL65M-240 MOQ applies)
PSAC60W-120-R	PPL65W-120
PSAC60W-240-R	PPL65W-240
PSA065-480-R	
POE90U-1BT-R	POE90U-1BT6-R
POE125U-8-C-R	
POE125U-8-N-R	
POE125U-4-AT-N-R	

Please do not hesitate to consult your Phihong contact if you should have any questions.

Sincerely,

Thomas Chin

Thomas Chin
Sr. Product Marketing Manager
Phihong USA Corp.