

Cooper Industries
Bussmann Division
P.O. Box 14460
St. Louis, MO 63178-4460



Subject: FWP

To all High Speed Fuse Users:

This letter is to inform you that a change has occurred in the part number for the Bussmann FWP High Speed Fuse product line. In accordance with internal ISO 9000 specifications, additional testing required by Bussmann for UL Recognition has mandated that a new part number must be designated for this series of fuses.

The FWP fuse's physical and electrical characteristics did not change. The only change was to have the fuse testing modified for UL Recognition purposes.

The old part number FWP-xxA14F has been changed to FWP-xxA14Fa. Therefore, if you had previously used an FWP-10A14F, you will now receive an FWP-10A14Fa. All FWP fuse orders that state the old part number will be changed to the new designation.

Catalog information, time current curves and I²t characteristics will remain the same.

If you have any questions, please contact Bussmann Application Engineering at (636) 527-1270.

Sincerely,
Bussmann High Speed Fuse Team

114 Old State Road
Ellisville, MO 63021-5942
(636) 394-2877