

Product Change Notice

Date:	March 5, 2020
Overview:	R2S133-AE17-43 to change from sleeve to ball bearings
Reason for Change:	Factory efficiency & streamlining - Simplification and more economic use of production equipment and single parts
Affected Part No(s):	R2S133-AE17-43
Design Change Detail:	The sleeve bearing system in the R2S133-AE17-43 is being changed to a ball bearing system
Effective Date:	Running change beginning at the end of Q2 / beginning of Q3 2020
Last Time Buy Deadline:	N/A
Pricing:	No change
ebm-papst employee:	Jeannine Zenobi
Attachments:	N/A
Comments:	Same form / fit / function / performance; ball bearings have been known to be more versatile for different mounting arrangements than sleeve bearings

Form No: 1274	Quality Record - No	Page 1 of 1
Rev. – Orig, Released 08/28/14	Retention Period – 1 year	Dept. Owner – Sales/Marketing