

Global Change Notification (GCN)

Product Family	SIM	10652230	
	5114	10052250	
		GCN Number	
Series	78790	September 03, 2014	
		Date Issued	
Reason For Change	Supplier Change		
Change Description	The purpose of this letter is to inform you that Molex Chengdu decide to change the outsource plating back to in house plating (from supplier to Molex Chengdu) due to poor quality performance of supplier. Part Number List Affected: 787901001		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-r	nail message.	
Reason For Short Notice Exception	Not Applicable		
Assessment Of Change (How Product Will Be Qualified & Validated)	Thickness FAI check Thickness CPK confirming Adhe Solderability test Overall cosmetic check Reeling dir		
Internal Molex Qualification Date (Planned Date Information Available)	July 23, 2014		
Sample Availability Date (Changed Part)	July 23, 2014		
Date of Implementation	February 01, 2015		
Method of Identifying Change	Date code from 2015-2-1		
Recommended Replacement Parts			
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com