AMPLEON

Customer Information Notification

2020080011

Issue Date: 05/08/2020 Effective Date:07/08/2020

Here is your personalized quality information concerning products our customers and partners purchased from Ampleon.

For detailed information we invite you to view this notification online

Management Summary

The datasheet published at release contained wrong info in table 8, capacitance values were interchanged Change Category

[] Wafer Fab process [] Assembly		[] Product Marking	[] Design
	Process		
[] Wafer Fab materials	[] Assembly Materials	[X] Electrical spec./Test coverage	[] Mechanical Specification
[] Wafer Fab locatio	n [] Assembly Location	[] Test Location	[] Packing/Shipping/Labeling

Datasheet update BLF984P, BLF984PS

Information Notification

The datasheet published at release contained wrong info in table 8, capacitance values were interchanged. Capacitor Crs was specified as 0.42pF and is now corrected to 35pF. Capacitor Coss was specified as 35pF and is now corrected to 0.42pF. The changes are only administrative and have no impact on the performance of the product.

Why do we issue this Information Notification

to inform customers on the correction in the datasheet

Identification of affected Products

Impact Data Sheet Revision

A new datasheet will be issued

Disposition of Old Products

not applicable

About Ampleon

Created in 2015, Ampleon is shaped by 50 years of RF power leadership and is set to exploit the full potential of data and energy transfer in RF. Ampleon has more than 1,250 employees worldwide, dedicated to creating optimal value for customers. Its innovative, yet consistent portfolio offers products and solutions for a wide range of applications, such as cellular base stations, radio/TV/broadcasting, radar, air traffic control, cooking, lighting, industrial lasers and medical. For details on the leading global partner in RF Power, visit www.ampleon.com.

You have received this email because you are a designated contact or registered to this portal. Ampleon shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.



Ampleon | Privacy Policy | Terms of Use

Ampleon

© 2020 Ampleon. All rights reserved.

Affected Part Numbers BLF984PU BLF984PSU