

Product Advisory

Issue Date: November 18, 2022

Change Type:

Packaging update for DCSG Storage adapters.

Description and Extent of Change:

The 96xx and 95xx adapter overpack kit count is increasing from five to ten per kit. For those SKUs with a Minimum Order Quantity (MOQ) of five, the MOQ will increase to ten. For other SKUs, the MOQ quantity will remain unchanged.

Reasons for Change:

The change is being implement to further enhance supply continuity and standardize overpack kit across the product line.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The adapter specification will remain the same. No changes to adapter form, fit, function, quality and reliability.

Effective Date of Change:

The part number revision will be incremented to track this update. Product shipments start after December 1, 2022.

Parts Affected:

Board Name	SKU Part Number	Current Rev No.	New Rev No.
9560-16i	05-50077-00	006	007
9500-8i	05-50077-03	002	003
9560-8i	05-50077-04	002	003
9560-8i	05-50077-05	002	003
9560-16i	05-50077-06	002	003
9500-8i	05-50077-07	002	003
9560-16i	05-50077-08	002	003
9560-8i	05-50077-09	001	002
9560-16i	05-50077-10	002	003
9500-8i	05-50077-11	002	003
9500-8i	05-50077-12	002	003
9580-8i8e	05-50076-00	003	004
9580-8e	05-50076-01	001	002
9580-8i8e	05-50076-02	002	003
9580-8e	05-50076-03	003	004
9500-16e	05-50075-00	003	004
9500-8e	05-50075-01	002	003
9500-16e	05-50075-02	002	003



9500-16e	05-50076-03	003	004
9500-8e	05-50076-04	002	003
9500-16e	05-50076-05	003	004
9500-16i	05-50134-00	001	002
9500-8i	05-50134-01	001	002
9540-16i	05-50134-02	001	002
9540-8i	05-50134-03	001	002
9500-16i	05-50134-04	001	002
9500-8i	05-50134-05	001	002
9540-16i	05-50134-06	001	002
9540-8i	05-50134-07	001	002
9540-8i	05-50134-08	001	002
9660-16i	05-50107-00	001	002
9670W-16i	05-50113-00	001	002
9670W-16i	05-50113-01	001	002
9600-16e	05-50118-00	001	002
9600W-16e	05-50108-00	001	002
9600W-16e	05-50108-01	001	002
9600W-16e	05-50108-02	001	002
9600-16i	05-50111-00	001	002
9600-24i	05-50111-01	001	002
9600-16i	05-50111-02	001	002
9600-24i	05-50111-03	001	002
9620-16i	05-50111-04	001	002
9600-16i	05-50111-05	001	002
9600-8i8e	05-50145-00	001	002
9540-2M2	05-50148-02	001	002
Remote Mount Board	L5-25376-00	B	C

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.