

(Product Discontinuance Notification)

Tuesday, February 14th PCN# 021323

To Whom It May Concern:

Please be advised that due to the unprecedented supply chain complications and environmental regulations impacting our business, NorComp must discontinue the list of part numbers shown on the subsequent pages of this notification.

The discontinuance is due to the challenges relating to the tin-plated shells used on the associated part numbers. All discontinued part numbers can be replaced by NorComp's standard nickel-plated shell equivalent part numbers (shown next to each discontinued part number on the subsequent pages). There are also alternative tin shelled part numbers provided for some of the parts being discontinued. All replacement part numbers meet the exact form, fit, and function of the discontinued part numbers except for the plating material on the shells.

All orders for the discontinued parts listed on the subsequent pages must be placed before Tuesday March 14th.

You are receiving this notification as our records show that you have purchased some of these products in the last 5 years. We appreciate your understanding as we strive to offer you the most current information regarding our product.

Please confirm receipt & acceptance of product change notification <u>by responding to this email</u>. If you have any questions or concerns, please feel free to contact us at <u>sales@norcomp.net</u>.

Regards,

Joshua Kadel Engineering Team Lead

Discontinued p/n	Replacement p/n	Alternative p/n
172-009-102R011	172-009-103R011	172-E09-103R011
172-009-102R021	172-009-103R021	172-E09-103R021
172-009-102R031	172-009-103R031	172-E09-103R031