

Product Change Notification

TE Connectivity

Product Change Notification: P-22-022120 PCN Date: 03-FEB-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

B-802, D-110, D-112, D-128, D-129. D-136, D-141, D-181, D-183, D-210, D-607, D-104, MK-0015, MK0020, D-150.

Description of Changes

SolderSleeve devices that required ROL1 flux were supplied with RILO flux.

Reason for Changes:

Document clarification. The PCN is to inform that SolderSleeve listed should be using ROL1 flux instead ROL0 flux were supplied. TE connectivity qualified ROL1 flux on August 27, 2021

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):		
	23-NOV-2021		
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):		
	No Mixed Shipments		

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>521076-000</u>	NO			"7-1194095-4"			
<u>625159-000</u>	NO			"2-1194948-7"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>521076-</u> <u>000</u>	NO			"7-1194095-4"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
625159- 000	NO			"2-1194948-7"			