

REFERENCE FORMAT FOR MATERIAL SAFETY DATA SHEET

1. Product and company information

Product name: N800A (Non-silicone Thermal Conductive Pad)

Product code: N800A

Names, addresses, and phone numbers of the manufacturer or supplier:

Shiu Li Technology Co., Ltd

No.435, Yongfeng Rd., Bade City, Taoyuan County 33455, Taiwan

Emergency contact phone numbers/fax numbers: +886-3-3788588

2. Ingredients identification information

English name: N800A (Non-silicone Thermal Conductive Pad)

Polyolefin : 10~30% (CAS No. 308070-21-5) Aluminum oxide: 90~70% (CAS No. 1344-28-1)

Synonyms:

The hazardous ingredient (% of the content):

Mixture:

The most

Chemical property:

Chinese and English names of The hazardous ingredients	concentration ranges (% of	Classification and hazard symbols of the hazardous material
-	-	-
-	-	-

3. Hazards identification information:

Adverse health effects: NO

Environmental effects: NO

Physical and chemical effects: NO

Important hazardous effect Specific hazards: NO

Main symptoms: NO

Hazard classification of the product: NO

4. First-aid Measures:

The first-aid measures for different exposure routes:

- Inhalation: Remove victim to fresh air. If cough or other respiratory symptoms develop, get medical attention. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Call a physician.
- Skin contact: Wash material with copious amounts of soap and water. Do not use solvents to clean skin. If irritation develops, get medical attention. Wash contaminated clothing and decontaminate footwear before reuse.
- Eye contact: Immediately flush with copious amounts of water for at least 15 minutes. Get medical attention.

Physical state: Paste Color: Pink Odor: PH value: Boiling point/boiling range: Flashpoint: Test method: Open cup/Close cup Auto ignition temperature: Vapor pressure: Vapor density: Density: 3.4 Solubility: 10. Stability and reactivity: Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	 Ingestion Rinse mouth with water. Give one or two anything by mouth to an unconscious or convuls 	
Notes to physicians: 5. Fire-fighting measures: Suitable fire extinguishing media: Water fog , dry chemical, foam, CO2 Specific fire-fighting methods: NO Specific fire-fighting methods: NO Specific fire-fighting methods: NO Special equipment for the protection of firefighters: NO 6. Accidental release measures: Remove all source of ignition. Wear appropriate personal protective equipment as specified in section 8. keep unnecessary and unprotected personnel away. Collect liquid in an appropriate container or absorb with an inert material (e.g., vermiculite, dry sand, earth), and place in a chemical waste container. Do not flush to sewer. 7. Safe handling and storage measures: Avoid skin and eye contact. Avoid breathing vapor, mist or spray. Wash thoroughly after handing. Remove contaminated clothing and wash before reuse. Keep container closed. Store in a cool, well ventilated place away from incompatible materials. 8. Exposure controls measures: Engineering control: The use of local exhaust ventilations is recommended to keep vapor as low as feasible. • Personal protective equipment: • Respiratory protection: • Skin and body protection: Wear and protect gloves Hygiene measures: 9. Physical and chemical properties: Physical state: Paste Color: Pink PH value: Decomposition temperature: Flashpoint: Test method: Open cup/Close cup Auto ignition temperature: Vapor pressure: Vapor density: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	The most important symptoms and hazardous effects: I	NO
5. Fire-fighting measures: Suitable fire extinguishing media: Water fog , dry chemical, foam, CO² Specific hazards may be encountered during fire-fighting: NO Specific fire-fighting methods: NO Special equipment for the protection of firefighters: NO 6. Accidental release measures: Remove all source of ignition. Wear appropriate personal protective equipment as specified in section 8. keep unnecessary and unprotected personnel away. Collect liquid in an appropriate container or absorb with an inert material (e.g., vermiculite, dry sand, earth), and place in a chemical waste container. Do not flush to sewer. 7. Safe handling and storage measures: Avoid skin and eye contact. Avoid breathing vapor, mist or spray. Wash thoroughly after handing. Remove contaminated clothing and wash before reuse. Keep container closed. Store in a cool, well ventilated place away from incompatible materials. 8. Exposure controls measures: Engineering control: The use of local exhaust ventilations is recommended to keep vapor as low as feasible. • Personal protective equipment: • Respiratory protection: • Hand protection: • Skin and body protection: Wear and protect gloves Hygiene measures: 9. Physical and chemical properties: Physical state: Paste Color: Pink PH value: Decomposition temperature: Fiashpoint: Test method: Open cup/Close cup Auto ignition temperature: Vapor pressure: Vapor pressure: Vapor density: Stability: 3.4 Solubility: Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	The protection of first-abiders:	
Suitable fire extinguishing media: Water fog , dry chemical, foam, CO² Specific hazards may be encountered during fire-fighting: NO Specific fire-fighting methods: NO Special equipment for the protection of firefighters: NO 6. Accidental release measures: Remove all source of ignition. Wear appropriate personal protective equipment as specified in section 8. keep unnecessary and unprotected personnel away. Collect liquid in an appropriate container or absorb with an inert material (e.g., vermiculite, dry sand, earth), and place in a chemical waste container. Do not flush to sewer. 7. Safe handling and storage measures: Avoid skin and eye contact. Avoid breathing vapor, mist or spray. Wash thoroughly after handing. Remove contaminated clothing and wash before reuse. Keep container closed. Store in a cool, well ventilated place away from incompatible materials. 8. Exposure controls measures: Engineering control: The use of local exhaust ventilations is recommended to keep vapor as low as feasible. • Personal protective equipment: • Respiratory protection: • Hand protection: • Skin and body protection: Wear and protect gloves Hygiene measures: 9. Physical and chemical properties: Physical state: Paste Color: Pink Odor: PH value: Decomposition temperature: Flashpoint: Test method: Open cup/Close cup Auto ignition temperature: Vapor pressure: Vapor pressure: Vapor pressure: Vapor pressure: Vapor pressure: Vapor density: Stablity: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Notes to physicians:	
Specific fire-fighting methods: NO Special equipment for the protection of firefighters: NO 6. Accidental release measures: Remove all source of ignition. Wear appropriate personal protective equipment as specified in section 8. keep unnecessary and unprotected personnel away. Collect liquid in an appropriate container or absorb with an inert material (e.g., vermiculite, dry sand, earth), and place in a chemical waste container. Do not flush to sewer. 7. Safe handling and storage measures: Avoid skin and eye contact. Avoid breathing vapor, mist or spray. Wash thoroughly after handing. Remove contaminated clothing and wash before reuse. Keep container closed. Store in a cool, well ventilated place away from incompatible materials. 8. Exposure controls measures: Engineering control: The use of local exhaust ventilations is recommended to keep vapor as low as feasible. Personal protective equipment: Respiratory protection: Hand protection: Fyer protection: Skin and body protection: Wear and protect gloves Hygiene measures: 9. Physical and chemical properties: Physical state: Paste Color: Pink Odor: Physical state: Paste Color: Pink Decomposition temperature: Flashpoint: Test method: Open cup/Close cup Auto ignition temperature: Explosion limits: Vapor pressure: Vapor pressure: Vapor density: Density: 3.4 O. Stability: 310. Stability and reactivity: Stability: Stabile under dry, room temperature conditions. Exothermic hardening reaction when mixed		ical, foam, CO ²
Special equipment for the protection of firefighters: NO 6. Accidental release measures: Remove all source of ignition. Wear appropriate personal protective equipment as specified in section seven unnecessary and unprotected personnel away. Collect liquid in an appropriate container or absorb with an inert material (e.g., vermiculite, dry sand, earth), and place in a chemical waste container. Do not flush to sewer. 7. Safe handling and storage measures: Avoid skin and eye contact. Avoid breathing vapor, mist or spray. Wash thoroughly after handing. Remove contaminated clothing and wash before reuse. Keep container closed. Store in a cool, well ventilated place away from incompatible materials. 8. Exposure controls measures: Engineering control: The use of local exhaust ventilations is recommended to keep vapor as low as feasible. • Personal protective equipment: • Respiratory protection: • Hand protection: • Bye protection: • Skin and body protection: Wear and protect gloves Hygiene measures: 9. Physical and chemical properties: Physical state: Paste Color: Pink PH value: Decomposition temperature: Flashpoint: Test method: Open cup/Close cup Auto ignition temperature: Explosion limits: Vapor pressure: Vapor density: Density: 3.4 10. Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Specific hazards may be encountered during fire-fighting	ng: NO
6. Accidental release measures: Remove all source of ignition. Wear appropriate personal protective equipment as specified in section 8. keep unnecessary and unprotected personnel away. Collect liquid in an appropriate container or absorb with an inert material (e.g., vermiculite, dry sand, earth), and place in a chemical waste container. Do not flush to sewer. 7. Safe handling and storage measures: Avoid skin and eye contact. Avoid breathing vapor, mist or spray. Wash thoroughly after handing. Remove contaminated clothing and wash before reuse. Keep container closed. Store in a cool, well ventilated place away from incompatible materials. 8. Exposure controls measures: Engineering control: The use of local exhaust ventilations is recommended to keep vapor as low as feasible. • Personal protective equipment: • Respiratory protection: • Hand protection: • Skin and body protection: Wear and protect gloves Hygiene measures: 9. Physical and chemical properties: Physical state: Paste Color: Pink Odor: Decomposition temperature: Decomposition temperature: Flashpoint: Test method: Open cup/Close cup Auto ignition temperature: Explosion limits: Vapor pressure: Density: 3.4 10. Stability and reactivity: Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Specific fire-fighting methods: NO	
Remove all source of ignition. Wear appropriate personal protective equipment as specified in section 8. keep unnecessary and unprotected personnel away. Collect liquid in an appropriate container or absorb with an inert material (e.g., vermiculite, dry sand, earth), and place in a chemical waste container. Do not flush to sewer. 7. Safe handling and storage measures: Avoid skin and eye contact. Avoid breathing vapor, mist or spray. Wash thoroughly after handing. Remove contaminated clothing and wash before reuse. Keep container closed. Store in a cool, well ventilated place away from incompatible materials. 8. Exposure controls measures: Engineering control: The use of local exhaust ventilations is recommended to keep vapor as low as feasible. • Personal protective equipment: • Respiratory protection: • Hand protection: • Eye protection: • Skin and body protection: Wear and protect gloves Hygiene measures: 9. Physical and chemical properties: Physical state: Paste Color: Pink Odor: PH value: Decomposition temperature: Flashpoint: Test method: Open cup/Close cup Auto ignition temperature: Vapor pressure: Density: 3.4 10. Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Special equipment for the protection of firefighters: NO	
Avoid skin and eye contact. Avoid breathing vapor, mist or spray. Wash thoroughly after handing. Remove contaminated clothing and wash before reuse. Keep container closed. Store in a cool, well ventilated place away from incompatible materials. 8. Exposure controls measures: Engineering control: The use of local exhaust ventilations is recommended to keep vapor as low as feasible. Personal protective equipment: Respiratory protection: Hand protection: Skin and body protection: Skin and protection: Skin and body protection: Skin and protect gloves Hygiene measures: Odor: Physical and chemical properties: Physical state: Paste Color: Pink Odor: PH value: Boiling point/boiling range: Flashpoint: Test method: Open cup/Close cup Auto ignition temperature: Vapor pressure: Vapor density: Vapor density: Density: 3.4 Solubility: 10. Stability and reactivity: Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Remove all source of ignition. Wear appropriate person 8. keep unnecessary and unprotected personnel away. absorb with an inert material (e.g., vermiculite, dry sand container. Do not flush to sewer.	Collect liquid in an appropriate container or
Engineering control: The use of local exhaust ventilations is recommended to keep vapor as low as feasible. Personal protective equipment: Respiratory protection: Hand protection: Skin and body protection: Skin and body protection: Skin and body protection: Skin and chemical properties: Physical and chemical properties: Physical state: Paste Color: Pink Odor: PH value: Boiling point/boiling range: Decomposition temperature: Flashpoint: Test method: Open cup/Close cup Auto ignition temperature: Vapor pressure: Vapor density: Density: 3.4 Solubility: Stability and reactivity: Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Avoid skin and eye contact. Avoid breathing vapor, miss Remove contaminated clothing and wash before reuse	
 Respiratory protection: Hand protection: Eye protection: Skin and body protection: Wear and protect gloves Hygiene measures: Physical and chemical properties: Physical state: Paste Color: Pink Odor: PH value: Boiling point/boiling range: Decomposition temperature: Flashpoint: Test method: Open cup/Close cup Auto ignition temperature: Explosion limits: Vapor pressure: Vapor density: Density: 3.4 Solubility: Solubility: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Engineering control: The use of local exhaust ventilatio	ns is recommended to keep vapor as low as
9. Physical and chemical properties: Physical state: Paste Color: Pink Odor: PH value: Boiling point/boiling range: Flashpoint: Test method: Open cup/Close cup Auto ignition temperature: Vapor pressure: Vapor density: Density: 3.4 Solubility: 10. Stability and reactivity: Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Respiratory protection:Hand protection:Eye protection:	ves
Physical state: Paste Color: Pink Odor: PH value: Boiling point/boiling range: Flashpoint: Test method: Open cup/Close cup Auto ignition temperature: Vapor pressure: Vapor density: Density: 3.4 Solubility: 10. Stability and reactivity: Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Hygiene measures:	
PH value: Decomposition temperature: Flashpoint: Test method: Open cup/Close cup Explosion limits: Vapor pressure: Vapor density: Density: 3.4 Solubility: 10. Stability and reactivity: Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Physical and chemical properties: Physical state: Paste	Form:
Decomposition temperature: Flashpoint: Test method: Open cup/Close cup Auto ignition temperature: Explosion limits: Vapor pressure: Vapor density: Density: 3.4 Solubility: 10. Stability and reactivity: Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Color: Pink	Odor:
Test method: Open cup/Close cup Auto ignition temperature: Vapor pressure: Vapor density: Density: 3.4 Solubility: 10. Stability and reactivity: Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	PH value:	Boiling point/boiling range:
Auto ignition temperature: Vapor pressure: Vapor density: Density: 3.4 Solubility: 10. Stability and reactivity: Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Decomposition temperature:	Flashpoint :
Vapor pressure: Density: 3.4 Solubility: 10. Stability and reactivity: Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed		Test method: Open cup/Close cup
Density: 3.4 Solubility: 10. Stability and reactivity: Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Auto ignition temperature:	Explosion limits:
10. Stability and reactivity: Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Vapor pressure:	Vapor density:
Stability: Stable under dry, room temperature conditions. Exothermic hardening reaction when mixed	Density: 3.4	Solubility:
with curing agents. 11. Toxicological information:	Stability: Stable under dry, room temperature conditions with curing agents.	s. Exothermic hardening reaction when mixed

旭立科技 Shiu Li Technology Co., Ltd 33455 桃園縣桃園市永豐路 435 號

No.435, Yongfeng Rd., Bade City, Taoyuan County 33455, Taiwan

TEL: +886-3-378-8588 FAX: +886-3-378-8288

Acute toxicity: NO
Local effects: NO
Sensitization: NO

Chronic toxicity or long term toxicity: NO

Specific effects: NO

12. Ecological information:

Possible environmental effects/environmental mobility: NO

13. Waste disposal measures:

Methods of waste disposal: The industry that retrieves raw materials person of silicon retrieves the waste material, there are regular recovery prices.

14. Transport information:

International regulations for transport: Not classified as hazardous under transport regulations (ADR RID ADNR IMDG / GGVSee ICAO / IATA)

United Nation number (UN No): Not applicable

Domestic regulations for transport: Not applicable

Specific transport measures and precautionary conditions: Not applicable

15. Regulatory information:

Applicable regulations: Taiwan. Methods and Facilities Standards for the Storage, Clearance and Disposal of Industrial Waste, Occupational Safety and Health Act.

16. Other information:

Literature References

Organization	Name: Shiu Li Technology Co.,Ltd
That prepared the MSDS	Address/Telephone: No.435, Yongfeng Rd., Bade City, Taoyuan County 33455, Taiwan TEL:+886-3-378-8588 FAX:+886-3-378-8288
Person who	Job title: Factory director
Prepared the MSDS	Name: (signature) Frank Jian
Date the MSDS	2021/02/08
Was prepared	

No.435, Yongfeng Rd., Bade City, Taoyuan County 33455, Taiwan

TEL: +886-3-378-8588 FAX: +886-3-378-8288