



End of Life of Specific parts from the M500IT family

PCN: 33766

Published: 2020-06-08

| | |
|--------------------------|---|
| Type: | End of Life |
| Description: | Micron will EOL the M500IT products included in this notification due to a lack of market demand. |
| Reason: | Change in Market Demand |
| Product Affected: | Specific M500IT parts listed below |

| Affected Micron Part Number Component | Recommended Replacement | Customer Part Number |
|--|-------------------------|----------------------|
| MTFDDAK064SBD-1AK12ITYY | | |
| MTFDDAK128SBD-1AK12ITYY | | |
| MTFDDAT128SBD-1AK12ITYY | | |

*Materials that have been ordered are in **bold**.

| | |
|----------------------------------|-----------------------|
| Method of Identification: | Marketing part number |
| Micron Sites Affected: | MSB - Singapore |
| Last Purchase Date*: | 2020-12-08 |
| Last Shipment Date: | 2021-06-08 |

Early placement of orders is encouraged as an increase in demand for this product could potentially exceed Micron's ability to meet all requests. All products from a previously accepted order that have not shipped as of the last-time purchase date will be considered non-cancelable and non-returnable. Changes to confirmed request dates will also require written approval by Micron. Should additional supply be available after the last-time purchase date, Micron may accept orders for product and such orders placed will be considered non-cancelable and non-returnable.

NOTE: Per JEDEC Standard J-STD-046 Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Attachments

There are no attachments on this PCN