

IloT Product Change Notice

The change(s) will be applied on the affected products, if you need more information or special support, please contact PM: Giorgio.Weii (TEL: +886-2-2792-7818, ext. 1150; e-Mail: giorgio.wei@advantech.com.tw).

1. Reason for the Change:

System reliability and PCI compatibility improvement.

2. Affected Product:

PCA-6028G2-00A1E, PCA-6028G2-00A2E, PCA-6028G2-CTA1,
PCA-6028VG-00A1E, PCA-6028VG-00A2E, PCA-6028VG-CTA1

3. Impact on Application:

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on Board Certifications ^{Note}	No
Physical Outlook Change	No
Ordering P/N Change	No
Cut-in Implement	New working order

Note: Advantech CE/FCC, UL/CB certifications on this product.

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
PCA-6028G2-00A1E PCA-6028G2-00A2E PCA-6028G2-CTA1 PCA-6028VG-00A1E PCA-6028VG-00A2E PCA-6028VG-CTA1	1410021700-11	1410028199-01	IC	Yes	1. Change PCIe to PCI bridge IC from IT8892 to IT8896.

5. Implementation & Schedule of the Change(s):

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
PCA-6028G2-00A1E PCA-6028G2-00A2E PCA-6028G2-CTA1 PCA-6028VG-00A1E PCA-6028VG-00A2E PCA-6028VG-CTA1	ECOM-185165	Feb, 2022	New working order	Replace 1410021700-11 with 1410028199-01

*Note: Cut-in progress depends on factory production schedule, what listed in this table is ESTIMATED time-frame.



Enabling an Intelligent Planet

研華股份有限公司
Advantech Co., Ltd.

台北市內湖區瑞光路26巷20弄1號
No.1, Alley 20, Lane 26, Rueiguang Road
Neihu, District, Taipei, Taiwan 114, R.O.C.
Tel: 886-2-2792-7818 Fax: 886-2-2794-7301
www.advantech.com

Contact Windows

PM	Giorgio Wei / giorgio.wei@advantech.com.tw / 511-1150
AE	AE.ISG.ACL@advantech.com

