

## Product Discontinuation

### PDN-MI-3425-2019

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
MI - Marking and Installation	BG3	Product Discontinuation	Notify Distributors and Field	4/8/2019

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

#### Description for Product Discontinuation

Discontinuation of the connector removal tools.  
Direct replacements available

#### Stock Status

Can existing stock still be used?      Yes  
Is mixture of stock acceptable?      No

#### Transaction Dates

Last Buy from Phoenix Contact:      4/8/2019  
Last Scheduled Ship from Phoenix Contact:      4/8/2019





## Product Discontinuation

*Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.*

**Contact Info:**

Maria Haynes  
mhaynes@phoenixcontact.com

Thank you,

---

Amy Dowell

Product Manager



Phoenix Contact Inc.  
P.O. BOX 4100  
Harrisburg, PA 17111-0100  
Phone: 717-944-1300  
Fax: 717-944-1625

## Product Discontinuation

Discontinued Part #	Type Description	Replacement Part #	Type Description
1662722	CK2,5-EWZ	1072067	UNIFOX RT-CK 2.5
1662735	CK4,0-EWZ	1072064	UNIFOX RT-CK 4.0
1884869	VC-EW 1,6	1072069	UNIFOX RT-CK 1.6