

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	012	0000002394	See list below	Appliance Outlet	5098	


*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected						
6182.0026	6182.0027	6182.0028	6182.0029	6182.0030	6182.0031	6182.0032
6182.0047	6182.0053					

2 Type of change

Change of approval and rating marks on the moulding body.

3 Detailed description of change



4 Reason of change

Standards update according to the new UL/CSA 60320-1

5 Release date

The change will be rolled out starting ww43/2019 (Date code 1943 or higher on packaging label) and lasts approx. 6 months depending on the variant. This change has no effect on the validity of the approval certificates.

6 Impact of change and recommended action

Form	Yes	Change of approval marks and rating.
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
5098 Data Sheet	

Product Change Notification					5098 Change of inscription		
owner	creation date	release date	released by	change order no	rev	page	D10-036-742
sariogar	16.05.2019	03.10.2019	blumhe	2017623	A	1 of 1	