## u·p·t·o·d·a·t·e Newsletter 🕸 🗖



January 17, 2020

## PTN

## Withdrawal of EPCOS switching spark gaps

To streamline the product range, the following EPCOS switching spark gaps manufactured in the plant in Johor Bahru/Malaysia are being withdrawn. Please contact your regional sales contact for alternative switching spark gaps.

## **Affected products**

Ordering code	Туре
B88069X0260T502	SSG3X-1
B88069X8061T602	FS08HF1BSMD
B88069X1303T502	FS08HF0B1A
B88069X1303S102	FS08HF0B1A
B88069X3173B252	FS08NSF0B1B2
B88069X4033T602	FS08HSF1BSMD

Deadline for last orders: April 24, 2020 Last shipments by: July 24, 2020

Contact Wong Huan Chee, PPD AB PM, Johor Bahru

Customers are asked to address inquiries directly to their sales contacts.