

1 Products affected


Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.
SBU PG PUG Type				·
02 007 012 0000001401	See list below	Connectors	Appliance Outlet 10A 6610-5	-
*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)			

List of part number	rs affected			
3-101-731	3-102-140	3-102-189	3-102-495	3-102-678
3-103-018	3-103-022	3-104-295	3-104-296	3-104-297
3-104-298	3-104-299	3-104-300	3-104-307	3-104-308
3-104-309	3-104-310	3-104-311	3-104-312	3-104-319
3-104-320				

2 Type of change

- Change of material
- Change of packaging label

3 Detailed description of change



4 Reason of change

- Material consolidation
- Appearance consolidation (colour of the front surface according to 4710-5)
- Configuration code changed because of enhanced glow wire requirements.

5 Release date

The change will be rolled-out starting ww 39/2018 (Date code 1839 or higher on label) and lasts approx. 6 months depending on the variant.

Product Change Notification				PCN 6610-5 - Change of Material				
owner	creation date	release date	released by	change order no	rev	page	D40 000 507	
vettersa	20.08.2018	20.09.2018	limachcl	2016087	Α	1 of 2	D10-028-587	



6 Impact of change and recommended action

Form Yes Appearance of colour
Fit No No change for dimension
Function No No change in function

Manufacturing No No change for manufacturing site Label Yes Configuration Code changed

Approval sign: CCC added to packaging label

Packaging No No change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	

Product Change Notification				PCN 6610-5 - Change of Material			
owner	creation date	release date	released by	change order no	rev	page	D40 000 507
vettersa	20.08.2018	20.09.2018	limachcl	2016087	Α	2 of 2	D10-028-587