

PRODUCT DISCONTINUATION

#PD-ICC-K8MO-16

Business Unit	Product Line Code	Type of Change	Action	Date of issue
ICC	BE1	Discontinuation	Notify Distributors and Field	2/23/2016

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

Because of production and technical reasons, the mentioned articles will be discontinued. Concerned products as well as substitute products are listed.

Discontinued product timeline:

Last order: 10/31/2016

Last shipment: 12/31/2016

Warranty Information:

N/A

Stock Status

Can existing stock still be used? Y

Is mixture of stock acceptable? N/A

Transaction Dates:

Last Buy from Phoenix Contact: 9/30/2016

Last Scheduled Ship from Phoenix Contact: 12/31/2016

PRODUCT DISCONTINUATION

Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

Alan Sappe'
 (717)944-1300x3386
 asappe@phoenixcon.com

Thank you,



William Schalon, Product Marketing Manager

Discontinued Part#	Type Description	Replacement Part#	Type Description
0316082	URTK/S M. ABGESCHNITT	0311087	URTK/S
3073924	UK 4-TG BK	3046142	UT 4-TG
3042078	UK 4-T-P/P BU MIT STECKER SN	N/A	N/A
3042065	UK 4-T-P/P MIT STECKER SN	N/A	N/A
3022014	UK 4-T	3046142	UT 4-TG
3042010	UK 4-T-P/P	3046168	UT 4-TG-P/P
2812034	UK 4-TG-P/P	3046168	UT 4-TG-P/P
2812018	UK 4-TG	3046142	UT 4-TG
1960013	UKB 4-FS/FS(4-2,8-0,8)	N/A	N/A
1960026	UKB 4-FS(2-2,8-0,8)	N/A	N/A