



Product Change Notice

Micron PCN: 31213
Date: 3/28/2014

Type of Change:	SSD Firmware Update
Title of Change:	Micron M500 Firmware Update Notification (MU05)

Description of Change: Firmware for the M500 (all form factors) is being updated from version MU03 to MU05. The M500 is upgradeable to this new firmware starting from previous versions using tools provided by Micron.

This update will be mandatory cut-in for new product built in Micron factories, and is an OPTIONAL update for any drive in the field. For end users, it is recommended if the user is experiencing or wishes to prevent an issue related to the following items.

- Improved Drive latency performance in applications with SMART polling.
- Improved Compatibility with 3rd party encryption management software.
- Corrected Reporting of SMART attribute 196 and 183.
- Increased thermal throttling response on 960GB Capacity for greater reliability.
- Corrected Upgrade issues experienced on MU03 by some customers.
- Numerous Bug fixes and stability improvements.

The firmware update tools for external bootable media and for Windows 7 will be available for internet download immediately. Download requires registration on the website. Please see <http://www.micron.com/ssdfirmware>.

Reason for Change:	Optimization of Manufacturing Efficiency, SSD Firmware Update
---------------------------	---

Contact Information:	<u>Marketing Contact</u> DELIA CARDENAS Micron Semiconductor Prds DECARDENAS@MICRON.COM	<u>Engineering Contact</u> DAVE GLEN Micron Technology, Inc. DGLEN@MICRON.COM
-----------------------------	---	--

Product Affected: Any 120GB, 240GB, 480GB or 960GB M500 SSD of any form factor, as indicated on product label.

Affected Micron Part Number

MTFDDAT120MAV-1AE12ABYY	MTFDDAV240MAV-1AE12ABYY	MTFDDAK480MAV-1AE12ABYY
MTFDDAT240MAV-1AE12ABYY	MTFDDAV480MAV-1AE12ABYY	MTFDDAK960MAV-1AE12ABYY
MTFDDAT480MAV-1AE12ABYY	MTFDDAK120MAV-1AE12ABYY	
MTFDDAV120MAV-1AE12ABYY	MTFDDAK240MAV-1AE12ABYY	



Method of Identification:

The M500 label will indicate the firmware revision.

- Current FW: MU03
- New FW: MU05

The current firmware can also be identified by interrogating detailed drive information, available in most operating systems. This firmware update will be available for download at <http://www.micron.com/ssdfirmware>.

Micron Sites Affected:	All Sites
Sample Available:	Now
Qual Data Available:	Now
Product Ship Date:	28-Apr-2014
