

PRODUCT DISCONTINUATION

PD-ION-55AR-15

| Business Unit | Product Line Code | Type of Change | Action | Date of issue |
|---------------|-------------------|-----------------|-------------------------------|---------------|
| ION | CNC | Discontinuation | Notify Distributors and Field | 11/17/2015 |

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

The following part has been discontinued and will no longer be available once stock reaches 0.

2885197 - RAD-CAB-PFP900-200

There is no direct replacement for this part, if a replacement is needed, please contact technical service for recommendations.

Warranty Information:

All factory warranties are valid

Stock Status

Can existing stock still be used? Y

Is mixture of stock acceptable? Y

Transaction Dates:

Last Buy from Phoenix Contact: When stock reaches 0

Last Scheduled Ship from Phoenix Contact: When stock reaches 0

PRODUCT DISCONTINUATION

Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

JUSTIN SHADE
(717)944-1300x3524
jshade@phoenixcon.com

Thank you,



Ira Sharp, Product Marketing Manager

| Discontinued Part# | Type Description | Replacement Part# | Type Description |
|--------------------|--------------------|-------------------|------------------|
| 2885197 | RAD-CAB-PFP900-200 | | |