



Not Recommended for New Design: EVP-ASEC1A & EVP-ASFC1A (Only)

NRFND.PG26.12.26.2018

12.26.2018

| | |
|--|---|
| About This Notice: | Two EVP-AS Series part numbers have changed status to Not Recommended For New Design. These two parts have operating life cycles of 100K cycles and have replacement parts available with long life. Please promote replacements into new design opportunities. |
| Features: | |
| Effective Date: | Immediate |
| Affected Parts and/or Replacements: | EVP-ASEC1A: Replace with EVP-ASKC1A EVP-ASFC1A: Replace with EVP-ASJC1A |
| Datasheet(s): | See attached. |
| Notes: | |