


PRODUCT CHANGE NOTIFICATION

Date Issued: August 9, 2019

Product Identification: Bel 0810 2x4, 2x6, 2x8 ICMs

PCN Number: PC2190078

Reason for Change (s): In an effort to continually improve our product, Bel is pleased to announce a modification to the front shield of the 0810 2xN ICMs in the specific area of the light-pipe and front shield. As shown below the gap between the light-pipe and shield is too small and can cause the shield to bend or become misaligned and create a snagging hazard. The solution is to remove the thin window frames from around the inside and bottom of the light-pipe.



The affected part numbers are:

Items	P/N	Items	P/N
1	08102H4RC8-F	10	08102H6R28-F
2	0810H2X4RHEF	11	08102H6RBG-F
3	08102H4R28-F	12	0810H2X6RL5F
4	08102H4RBGAF	13	08102H6VBGAF
5	08102H4RBG-F	14	08102H6VBG-F
6	08102H4NN9-F	15	08102H6VBGBF
7	08102H4RDF-F	16	08102H8R28-F
8	08102H4RN9-F	17	08102H8RB8-F
9	08102G6R28-F	18	08102H8RN9-F

These changes will not affect "form, fit, or function", nor do they affect any other dimensions or electrical parameters of the part. No other related changes to the above series are being implemented at this time.

Description of the Change (s): To resolve the assembly issue and deformation of the shield around the light-pipe, the thin, shield window frames around the inside and bottom of the light-pipe will be removed. By removing these thin metal pieces, the limited gap issue will be resolved and there will not be a concern for shield deformation. Please see the details below.

