



# Product Change Notification

## TE Connectivity


Product Change Notification: P-17-014161

PCN Date: 16-FEB-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:  
Micro K THT/THR relays

Description of Changes  
Please disregard PCN P-16-013889. "Introduction of an offline riveting machine to allow the production of relays with offline riveted springs in all lines". By mistake listed PNs are not affected by mentioned change. We would like to apologize for any inconvenience caused by this.



Reason for Changes:  
Product improvement. By mistake listed PNs are not affected by mentioned change. We would like to apologize for any inconvenience caused by this.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1414760-0</a>	NO			"V23086-C1021-A502-EV-USBX"			
<a href="#">1393280-5</a>	NO			"V23086C1001A402"			
<a href="#">2-1904093-1</a>	NO						
<a href="#">9-1904064-4</a>	NO			"V23086-R1851-A502"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1414760-0</a>	NO			"V23086-C1021-A502-EV-USBX"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1393280-5</a>	NO			"V23086C1001A402"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1393280-5</a>	NO			"V23086C1001A402"			
<a href="#">9-1904064-4</a>	NO			"V23086-R1851-A502"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1414760-0</a>	NO			"V23086-C1021-A502-EV-USBX"			
<a href="#">1393280-5</a>	NO			"V23086C1001A402"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1393280-5</a>	NO			"V23086C1001A402"			
<a href="#">2-1904093-1</a>	NO						
<a href="#">9-1904064-4</a>	NO			"V23086-R1851-A502"			